

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-77

3a. Indicate Type of Lease  
State ☐ For ☒  
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Roger C. Hanks	8. Farm or Lease Name C. M. Graham
3. Address of Operator P.O. Box 3148 Midland, Texas 79702	9. Well No. 2
4. Location of Well UNIT LETTER <u>RL</u> 660 FEET FROM THE West LINE AND 1980 FEET FROM THE South LINE, SECTION 29 TOWNSHIP 16S RANGE 36E NMPM.	10. Field and Pool, or Wildcat Shoe Bar East
15. Elevation (Show whether DF, RT, GR, etc.) 3927 GL	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-15-77 RU D.A. & S. Well Servicing Unit  
6-17-77 Set CIBP @ 12,900' w/4 sx Cmt - 35' on top of CIBP  
6-20-77 Shot csg @ 4485' - Recovered 140 jts 5 1/2" csg  
6-23-77 Ran tbq - set 1st plug @ 4535' w/ 30 sx cmt. Set 2nd plug @ 4320' w/ 45 sx cmt  
6-24-77 Shot 8 1/2" csg @ 1250' - came free - Recovered 28 jts 8 5/8" csg. Set 3rd plug @ 1300' w/ 55 sx cmt. Set plug #4 @ 464' w/80 sx cmt.  
Set surface plug w/20 sx cmt. RD unit. Set surface marker.  
Cleaned location. Final P&A 6-27-77.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Maurice Ford TITLE Production Clerk DATE 4-14-81

APPROVED BY RD Peterson TITLE OIL & GAS INSPECTOR DATE APR 2 1981

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 16 '81

OIL CONSERVATION DIV.