

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator GREAT WESTERN DRILLING COMPANY		8. Farm or Lease Name E. L. HARROD
3. Address of Operator BOX 1659 MIDLAND TEXAS 79701		9. Well No. 1
4. Location of Well UNIT LETTER I 1980 FEET FROM THE SOUTH LINE AND 660 FEET FROM THE EAST LINE, SECTION 7 TOWNSHIP 16-S RANGE 35-E N.M.P.M.		10. Field and Pool, or Wildcat EIDSON PENN
15. Elevation (Show whether DF, RT, GR, etc.) 4039.9 GR		12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The hole will be filled with a mud-laden fluid and a 25 sack plug placed across the 4½" casing perforations from 10,718' to 10,746'. An attempt will be made to pull some 10,000' of 4½" csg. and 2,000' of 8 5/8" casing. Additional cement plugs will be placed as follows:

25 sacks 50' into 4½" casing stub at approximately 10,000'
35 sacks at 9800' to 9900'
35 sacks at 8150' to 8250'
50 sacks at 7475' to 7625'
60 sacks at 6520' to 6690'
35 sacks at 6200' to 6300'
35 sacks across the 8 5/8" casing shoe at 4660'
60 sacks 50' into the 8 5/8" casing stub at approx. 2000'
70 sacks across the 13 3/8" casing shoe
10 sacks at the surface

A permanent marker will be set and a location cleanup made.

24 hr notice

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R.I. Comstock TITLE Chief Engineer DATE June 12, 1973

APPROVED BY John J. [Signature] TITLE Inspector DATE June 12, 1973

CONDITIONS OF APPROVAL, IF ANY: