## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES ACCCIVED		
DISTRIBUTION		
SANTA FE		1
アルス		
V.3.0.5.		1
LAND OFFICE		1
03.00	$\neg$	

## OIL CONSERVATION DIVISION P. O. BOX 2088

Form	C-	103	
Revis	ed	10-	1 -

SANTA FE, NEW MEXICO 87501	Revised 19-1-
U.3.G.S,	5u. Indicate Type of Lease
LAND OFFICE OPERATOR	State Fee X
TOPENT OF	5, State Oil & Gas Leaso No.
SUNDRY NOTICES AND REPORTS ON WELLS	- invinnimme
SUNDRY NOTICES AND REPORTS ON WELLS  100 HOT USE THIS FORM FOR PROPOSALS TO DRILL ON TO DEFEN OF PLUS SACE TO A DIFFERENT RESERVOIR.	
	7. Unit Agreement Name
OIL GAS WELL X OTHER-	
Amoco Production Company	8. Farm or Lease Name
3, Address of Operator	Anderson 3 Com
P. O. Box 68, Hobbs, New Mexico 88240	1
1. Location of Well 1830	10. Field and Pool, or Wildcat
UNIT LETTER R , 1930 FEET FROM THE SOUTH LINE AND 1980 FEET	Anderson Ranch Morrow
THE East LINE, SECTION 3 TOWNSHIP 16-S RANGE 32-E	MPM. ([]]]]]]]]
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
4329' GR	Lea
Check Appropriate Box To Indicate Nature of Notice, Report of	or Other Data
	JENT REPORT OF:
	_
TENERS AND ABANDON REMEDIAL WORK	ALTERING CASING
PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT
OTHER	, ,
OTHER	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, included) SEE RULE 1103.	
Moved in service unit 1-6-82. Ran swab with initial fluid level and recovered 25 BW in 3 hrs. Acidized with 3000 gal 7-1/2% HCL hrs. and recovered 16 BC and 243 BLW. Moved out swab unit 1-11-8 unit 1-27-82. Ran swab with initial fluid level at 4500'. Recovering 25 hrs. with a small show of gas. Moved out service unit 1-25 service unit 2-1-82. Pulled up 50 joints of tubing and tubing parand recovered 114 joints. Ran on-off tool, crossover, bumper swall and tubing. Latched onto fish at 12300' Released packer and pull and tools. Ran tubing and tubing landed at 9975'. Set anchor an Ran rods and pump. Moved out service unit 2-16-82. Pump tested for 390 BO, 627 BW, and 300 MCF. Returned well to production.	MS. Ran swab for 53 32. Rigged up swab ered 138 BW and 94 BO 9-82. Rigged up erted. Pulled tubing ab,jars, drill collars, led tubing, packer,
is. I hereov certify that the information above is true and complete to the best of my knowledge and belief.	
Assist. Admin. Analys	t 3-5-82
ORIGINAL SIGNED BY	UATE
JERRY SEXTON	MAR 9 1982
APPROVED BY DISTRICT 1 SUPR. TITLE	MAR 9 1982
CONDITIONS OF APPROVAL, IF ANY!	