

9. Cut off wellhead and casing 3' below ground level. Weld a steel plate with a ball valve onto the casing. Install dryhole marker with name and location of well. Clean up the location and haul equipment to the yard.

Cement Properties: Class "C" 14.8 ppg, 6.3 gwps, 1.32 cfps

kbc/valplug.doc