

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
30-025-29415

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</p>			
<p>1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER</p>		7. Lease Name or Unit Agreement Name ANDRUS 9	
2. Name of Operator Amerada Hess Corporation		8. Well No. 1	
3. Address of Operator P. O. Drawer D, Monument, NM 88265		9. Pool name or Wildcat N.E. LOVINGTON PENN	
4. Well Location Unit Letter <u>L</u> : <u>1874</u> Feet From The <u>SOUTH</u> Line and <u>766</u> Feet From The <u>WEST</u> Line			
Section <u>9</u>		Township <u>16S</u> Range <u>37E</u> NMPM LEA County	
		10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3823' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK PLUG AND ABANDON

TEMPORARILY ABANDON CHANGE PLANS

PULL OR ALTER CASING

OTHER: _____

SUBSEQUENT REPORT OF:

REMEDIAL WORK ALTERING CASING

COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT

CASING TEST AND CEMENT JOB

OTHER: _____

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to MIRU pulling unit & TOH laying down rods & pump. Remove wellhead & install BOP. Release TAC & TOH w/tbg. TIH w/gauge ring to 11500'. TIH w/CIBP set at 11480'. Dump bail 35' cement on top CIBP. Install 11" BOPS on csg. head. Freepoint 5-1/2" csg. & jet cut 5-1/2" csg. LD 5-1/2" csg. TIH w/tbg. to 11400' & circ. hole w/plug mud. TOH w/tbg. to 9000' & spot 100' balanced cement plug. TOH w/tbg. to 6500' & spot 100' balanced cement plug. TOH w/tbg. to 5135' & spot 100' balanced cement plug. TOH w/tbg. & spot 100' balanced cement plug across 5-1/2" csg. stub. TOH to 2250' & spot 100' plug above salt. Spot 10 sx. surface plug. Cut off wellhead & install dry hole marker. Cut off deadman anchors, clean & abandon location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE R. L. Wheeler, Jr. TITLE Admin. Svc. Coord. DATE 3-14-96

TYPE OR PRINT NAME R. L. Wheeler, Jr. TELEPHONE NO. 505 393-2144

(This space for State Use)

ORIGINAL COPIES BY TERRY DENTON
DISTRICT I SUPERVISOR

MAR 18 1996

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: