

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-07352
Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
*State Oil & Gas Lease No.

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</p>	
Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	*Lease Name or Unit Agreement Name HARDIN B
*Name of Operator CROSS TIMBERS OPERATING COMPANY	*Well No. 2
*Address of Operator 3000 N. GARFIELD, SUITE 175, MIDLAND, TEXAS 79705	*Pool name or Wildcat HOBBS GRAYBURG SAN ANDRES
*Well Location Unit Letter <u>F</u> : <u>2310</u> Feet From The <u>NORTH</u> Line and <u>2230</u> Feet From The <u>WEST</u> Line Section <u>18</u> Township <u>18S</u> Range <u>38E</u> NMPM <u>LEA</u> County	
*Elevation (Show whether DF, RKB, RT, GR, etc.) 3665' KB	

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ANBANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

*Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- SET 5-1/2" CIBP @ 4000'.
- DUMP 35' CEMENT ON TOP OF CIBP.
- CIRC HOLE W/10# BRINE WATER.
- SPOT 100' CEMENT PLUG AT 1550'-1650'.
- SPOT 100' CEMENT PLUG AT 188'-288'.
- CUT OFF WELLHEAD AND SURCFACE CSG, SET 10 SX CEMENT IN TOP OF SURFACE CSG, WELD ON PLATE & INSTALL DRY HOLE MARKER.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mark A. Gosch TITLE DRILLING ENGINEER DATE 07-23-97

TYPE OR PRINT NAME MARK A. GOSCH TELEPHONE NO. 915-682-8873

(This space for State Use)
ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

JUL 30 1997