

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
30-025-07363

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name
N. HOBBS (G/SA) UNIT
SECTION 19

1. Type of Well:
OIL WELL GAS WELL OTHER

8. Well No.
331

2. Name of Operator
Shell Western E&P Inc.

9. Pool name or Wildcat
HOBBS (G/SA)

3. Address of Operator
P.O. Box 576 Houston, TX 77001-0576

4. Well Location
Unit Letter J : 2310 Feet From The SOUTH Line and 2310 Feet From The EAST Line
Section 19 Township 18S Range 38E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3661' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <u>OAP & ACD</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-04 TO 3-16-92:

POH W/PROD EQMT. CO TO CIBP @ 4104'. SET CIBP @ 4070'. PERF SA 4033-48' (2 SPF).
ATTMPTD TO ACD PERFS 4033-48' W/1512 GAL 15% NEFE HCL. HAD DIFFICULTY BRKG DN PERFS.
DRILD UP CIBP'S @ 4070' & 4104'. POH, LEFT BTM OF SD LINE DRILL IN HOLE. RIH W/
3-3/4 IN. TAPER TAP. POH W/FISH. MLD UP CIBP REMNANTS @ 4104' & PUSH TO BTM. SET CIBP @
4140'. PERF SA 4101-16' (2 SPF). ACD PERFS 4101-16' W/1250 GAL 15% NEFE HCL. INST
PROD EQMT & RTP.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE TECH. MANAGER - ENVIR. ENG. DATE 5/20/92

TYPE OR PRINT NAME W. F. N. KELLDORF TELEPHONE NO. 713/870-3426

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

MAY 27 '92

RECEIVED

MAY 26 1992

RECEIVED
OCD HOBBS OFFICE

MAY 26 1992

OCD HOBBS OFFICE