

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-07397
Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			
Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		Lease Name or Unit Agreement Name North Hobbs (G/SA) Unit	
Name of Operator Altura Energy, LTD		Well No. 441	
Address of Operator 1017 Stanolind Rd. Hobbs, New Mexico 88240		Pool name or Wildcat Hobbs (G/SA)	
Well Location Unit Letter <u>P</u> : <u>230</u> Feet From The <u>South</u> Line and <u>1090</u> Feet From The <u>East</u> Line Section <u>21</u> Township <u>18-S</u> Range <u>38-E</u> NMPM <u>Lea</u> County			
		Elevation (Show whether DF, RKB, RT, GR, etc.)	

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ANBANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

03-02-00 Notify EMNRD-OCD of intent to plug
 03-02-00 Tag CIBP @ 4040'
 03-02-00 Spot 35 sxs cmt on CIBP @ 4040'
 03-02-00 Spot 25 sxs cmt @ 2810'
 03-03-00 Tag plug @ 2490'
 03-03-00 Perf 4 holes @ 2000'; set pkr @ 1700'; squeeze 35 sxs cmt; WOC; Tag @ 1875'
 03-03-00 Perf 4 holes @ 310'; set pkr @ 30'; squeeze 110 sxs cmt
 03-06-00 Tag plug @ 178'
 03-06-00 Spot 10 sxs cmt from 30' to surface
 03-07-00 Cut off wellhead, install dry hole marker, and clean location

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Key Energy, P & A Supervisor DATE 03-07-00

TYPE OR PRINT NAME Larry Winn. TELEPHONE NO. (915) 523-5155

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE NOV 9 2000

CONDITIONS OF APPROVAL, IF ANY: GWW