

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 300250954 - <i>Incorrect</i>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1031
7. Lease Name or Unit Agreement Name Central Vacuum Unit
8. Well No. 117
9. Pool name or Wildcat Vacuum Grayburg San Andres

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Texaco Producing Inc.
3. Address of Operator P.O. Box 730, Hobbs, NM 88240
4. Well Location Unit Letter <u>0</u> : <u>990</u> Feet From The <u>South</u> Line and <u>2310</u> Feet From The <u>East</u> Line Section <u>6</u> Township <u>18S</u> Range <u>35E</u> NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3980' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Central Vacuum Unit Well No. 117
Proposed Plugging Procedures

- 1). Backflow well.
- 2). MIRU pulling unit. Install BOP. - 4450
- 3). Spot 35 ft (2 sxs class "C") on CIBP.
- 4). RIH with tubing to PBTD. Fill hole with salt gel mud (10 lb. brine with 25 lbs. of gel per barrel).
- 5). Spot 50 sx plug of class "C" cement from 2620 ft to 1505 ft.
- 6). Spot 10 sx plug of class "C" cement at surface.
- 7). Cut off well. Install marker. Rig down pulling unit. Clean location.

8 100' plug @ 300-400'

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Richard DeSoto TITLE Engineering Technician DATE 07/20/90

TYPE OR PRINT NAME R. B. DeSoto TELEPHONE NO. 393-7191

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE JUL 25 1990

CONDITIONS OF APPROVAL, IF ANY:

THE COMMISSION MUST BE NOTICED 24 HOURS PRIOR TO THE BEGINNING OF PRODUCE OPERATIONS FOR THE WELL