

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103

Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐
6. State Oil & Gas Lease No.
1-6901

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR PLUG OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name
2. Name of Operator DINERO OPERATING COMPANY	8. Field or Lease Name MESA MERRITT STATE
3. Address of Operator POST OFFICE DRAWER 10505, MIDLAND, TEXAS 79701	9. Well No. 1
4. Location of Well UNIT LETTER F 1980 FEET FROM THE North LINE AND 1980 FEET FROM West LINE, SECTION 19 TOWNSHIP 18-N RANGE 35-E	10. Field and Loc., or Wildcat Wildcat-Airstrip
11. Elevation (show whether br., RT, GR, etc.) 3959 G.L.	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
 TEMPORARILY ABANDON ☐
 PULL OR ALTER CASING ☐
 OTHER ☐

PLUG AND ABANDON ☒
 CHANGE PLANS ☐
 OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
 COMMENCE DRILLING OPNS. ☐
 CASING TEST AND CEMENT JOB ☐
 OTHER ☐
 ALTERING CASING ☐
 PLUG AND ABANDONMENT ☐

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

We propose to plug & abandon the Messa Merritt as follows:

Set CIPB @ 10,000' with 20 foot of cement on top of plug. Run free point on 4½ casing and cut where it is free. Top of cement outside 8,005.70', cut at 7,500' and pull casing out of hole.

Run tubing in hole to 7,230', spot 40 sack plug up to 7,130', tag top of Bone Spring. Pull tubing up to 5,300', spot 40 sack plug up to 5,200'-top of San Anders. Pull tubing up to 4,898', spot 70 sack plug up to 4,710'-8 5/8 shoe.

8 5/8 casing perforated @ 4616-26, zone was non-commercial, spot 50 sack across perf. zone and tag with tubing.

8 5/8 is cut off at 704'-spot 50 sacks 754 up to 654'
 spot 66 sacks-460' up to 360'

10 sacks at surface and install dryhole marker

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103

14. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Lavonda Norman *Lavonda Norman* TITLE Production Supervisor

DATE March 30, 1982

ORIGINAL SIGNED BY

APPROVED BY JERRY SEXTON

CONDITIONS OF APPROVAL DISTRICT 1 SUPR.

TITLE

DATE

APR 2 1982

RECEIVED

APR 1 1982

O.C.D.
HIGHER OFFICE