

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. <u>30-025-29489</u>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LG-3229
7. Lease Name or Unit Agreement Name ABO "13" State
8. Well No. 1
9. Pool name or Wildcat Reeves (Bone Spring)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Mitchell Energy Corporation	
3. Address of Operator P. O. Box 4000, The Woodlands, TX 77387-4000	
4. Well Location Unit Letter <u>D</u> : <u>660</u> Feet From The <u>North</u> Line and <u>330</u> Feet From The <u>West</u> Line Section <u>13</u> Township <u>18S</u> Range <u>35E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3881' GR</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU PU. POOH w/rods & 2 7/8" tbg. RIH w/CIBP & set @ 8500'. Dump ^{35'} of cmt on top. Load hole w/9.5# mud. RIH w/csg cutter & cut off 5 1/2" csg @ ±5200'. POOH w/5 1/2" csg. RIH w/tbg & spot 100' cmt plug across 5 1/2" csg top @ ±5200'. Pull up & spot 100' plug across 8 5/8" shoe @ 3785'. PU & spot 100' cmt plug in 8 5/8" csg @ top of salt from 1770-1870'. Spot 50 sx surface plug & erect P&A marker. RDMO PU.

ALL INFORMATION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF THE OPERATION AND THE CLOSURE OF THE WELL.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James Blount TITLE Engineer DATE 5/13/93

TYPE OR PRINT NAME James Blount

TELEPHONE NO. 915-682-5396

(This space for State Use)

ORIGINAL SIGNED BY JEFFY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE MAY 20 1993

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAY 19 1993

AND HORNS DEPT