to Appropriate	Energy, Minerals and Natural F	Passumes Denartment	Form C-103	
District Office			Revised 1-1-89	
DISTRICT 1 P.O. Bax 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION P.O. Box 2088		WELL API NO. 30-025-30608	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico	87504-2088	5. Indicate Type of Lease STATE X FEE	
DISTRICT III 1000 Rio Brazos Rd., Azzec, NIM 87410			6. State Oil & Gas Lease No. IG-6631	
( DO NOT USE THIS FORM FOR PROPERTY RESERVE	CES AND REPORTS ON WE POSALS TO DRILL OR TO DEEPE VOIR. USE "APPLICATION FOR P 101) FOR SUCH PROPOSALS.)	N OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name	
1. Type of Well: OR. OAS WELL WELL	OTHER		Cal-Mon 15 State	
2 Name of Operator Harvey E. Yates C	ompany		8. Well No. #1	
3. Address of Operator P.O. Box 1933, R	oswell, N.M. 88202		9. Pool name or Wildcat Mescalero Escarpe Bone Spring	
4. Well Location Unit Letter D _ ; 660	Feet From The North	Line and 990		
Section 15	Township 18S	Range 33E	NMPM Lea County	
	/////	er DF, RKB, RT, GR, etc.) 3926.4 GL		
11. Check A NOTICE OF INT	Appropriate Box to Indicate ENTION TO:	Nature of Notice, R	Leport, or Other Data  SSEQUENT REPORT OF:	
PERFORM REMEDIAL WOFIK	PLUG AND ABANDON	REMEDIAL WORK	X ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLIN	G OPNS. PLUG AND ABANDONMENT	
PULL OR ALTER CASING		CASING TEST AND C	EMENT JOB L	
OTHER:		OTHER:		

SEE ATTACHMENT

CONDITIONS OF APPROVAL, IP ANY:

I hereby certify that the information above is true and complete to the best of my knowled	ge and belief. Production Analyst	3/5/91
Vickie Teel Type or print name  Vickie Teel  Drig. Signed by		телерноме No. 623-6601
(This space for State Use)  Raul Kautz Geologist	— TITLE ————————————————————————————————————	MAR 6 8 1991

HARVEY E. YATES COMPANY
CAL-MON 15 STATE #1
660' FNL & 990' FWL
Sec. 15, T18S, R33E,
Lea County, New Mexico

12/15/89	RU L&R WS, PMP STUCK IN TBG, BACK OFF RODS, NU BOP & START STRIPPING OOH W/RODS & TBG
12/16/89	FIN STRIPPING OOH W/TBG & RODS, GIH W/SN, 40 JTS 2 3/8 TBG, ANCHOR & 263 JTS TBG, ND BOP, SET ANCHOR
12/17/89	(40 JTS OFF BTM), NU TREE, SDFN GIH W/2" X 1 1/2" X 16' PMP, 1-2'x 3/4" PONY, 262-3/4" & 116-7/8" RODS, 1-6'x 7/8", 2-4'x 7/8" &
	1-2'x 7/8" PONIES, SPACE OUT & HANG ON
02/09/90	RU REAL WELL SERV, UNSEAT PMP & SOOH, SI, SDFN
02/10/90	FIN POOH W/RODS & PMP, GIH W/2" x 1 1/2" x 16' PMP &
	RODS, HANG ON, GOOD PMP ACTION, RD
04/12/90	MI & RU L&R, WORK W/PMP, COULD NOT UNSET, BACK RODS OFF ON TOP OF PMP & PULL RODS, UNSEAT TA, RU BOP &
	PULL 28 JTS TBG, SDFN
04/13/90	FIN PULLING TBG, KNOCK SEATING CUPS OUT OF SN, RUN TBG BACK IN HOLE, RD BOP, NU WH, RAN 2" x 1 1/2" x
	16' PMP & RODS, CHECK PMP ACTION, PUT BACK ON
02/22/91	MI & RU PRIDE, WORK W/PMP & UNSEAT, PULL RODS & PMP, HOT OIL TBG W/75 BBLS, RUN 2" x 1 1/2" x 16' PMP,
	271-3/4" & 134-7/8" RODS, SPACE OUT & HANG ON PROD,
	RD