

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-30717

5. Indicate Type of Lease

STATE ☒FEE ☐

6. State Oil / Gas Lease No.

B - 1080

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator

TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator

PO BOX 3109, MIDLAND, TX 79702

4. Well Location

Unit Letter C : 710 Feet From The NORTH Line and 2530 Feet From The WEST LineSection 1 Township 18S Range 34E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

GR-3993'

7. Lease Name or Unit Agreement Name

VACUUM GRAYBURG SAN ANDRES UNIT

8. Well No.

157

9. Pool Name or Wildcat

VACUUM GRAYBURG SAN ANDRES

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:PERFORM REMEDIAL WORK ☐PLUG AND ABANDON ☐TEMPORARILY ABANDON ☐CHANGE PLANS ☐PULL OR ALTER CASING ☐OTHER: ☐**SUBSEQUENT REPORT OF:**REMEDIAL WORK ☒ALTERING CASING ☐COMMENCE DRILLING OPERATION ☐PLUG AND ABANDONMENT ☐CASING TEST AND CEMENT JOB ☐OTHER: ☐RE-ESTABLISH TA'D WELLBORE ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-21-01: MIRU. RU FLOW LINE.

9-24-01: NDWH. NUBOP. TIH W/BIT, DC'S & WS. TAG @ 4072. TEST CSG TO 585 -OK. DISPL W/10# BRINE. DRILL CIBP @ 4072. DRILL PLUG & PUSH TO 4090.

9-25-01: LOWER BIT. PUSH CIBP TO 4395. DRILL CIBP & CMT 135' TO 4530. TIH W/NEW BIT TO 1400'.

9-26-01: TAG CMT @ 4530. DRILL 75' CMT TO 4605. TAG CIBP @ 4605. DRILL CIBP. TURN LOOSE. PUSH TO 4920. DRILL CIBP & FILL TO 4962. DISPL HLE W/185 BBLs BW.

9-27-01: NDBOP. NU MANUAL BOP. RIG DOWN KEY.

10-23-01: MIRU KEY. SET FRAC TANKS.

10-24-01: TIH W/WS. TAG @ PBTD @ 4962.

10-25-01: TIH W/PERF GUNS & PERF SAN ANDRES FORMATION 4280-4350, 4430-4470, 4496-4512, 4524-4556, 4562-4574, 4610-4620, 4664-4670, 4676-4680.

10-26-01: TIH W/HEGGS GUN & PERF 4178-4182, 4194-4198, 4204-4212, 4230-4250, 4254-4258. TIH W/PKR, SN & WS TO 4415. SET PKR. PUMP DN TBG.

10-29-01: ATTEMPT TO ACIDIZE SAN ANDRES PERFS 4430-4680 W/4500 GALS 15% NEFE HCL. ESTAB INUJ RATE @ 3 BPM @ 1500 PSI.

PUMP 500 GALS 15% ACID. & 1302 GALS 15% ACID. ENCOUNTER COMMUNICATION W/UPPER PERFS. REL PKR. SET PKR @ 4111. ACIDIZE ALL PERFS 4178-4680 W/8188 GALS 15% NEFE HCL.

10-30-01: RU SWAB. REL PKR @ 4111. TIH TO 4731. SET PKR.

10-31-01: OPEN TBG. PUMP MAGNATREAT M IN VGSAU FORMATION 4178-4680. START INJECTION MAG M W/100 BBLs. RIG DOWN.

11-06-01: RU SWAB. REL PKR.

11-09-01: TIH W/3 SAND FILTERS, MOTOR, SEALS, GAS SEPR, PUMP, TBG. BTM OF STRING @ 13' @ 4021. HU FLOWLINE. START UP WELL.

11-12-01: RIG DOWN.

11-19-01: ON 24 HR OPT. PUMPED 10 BO, 336 BW, & 24 MCF. PERFS 4178-4680. FINAL REPORT

This Approval of Temporary
Abandonment Expires

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

Engineering Assistant

DATE

1/9/02

TYPE OR PRINT NAME

J. Denise Leake

Telephone No.

915-688-4752

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL IF ANY:

TITLE

DATE

JAN 15 2002

DeSoto/Nichols 12-93 ver 1.0