

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO. 30-025-31954
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-2040
7. Lease Name or Unit Agreement Name: EKAY 28 STATE
8. Well No. 3
9. Pool name or Wildcat DIOS MANO DELAWARE


SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	
2. Name of Operator Harvey E. Yates Company	
3. Address of Operator P.O. Box 1933, Roswell, New Mexico 88202	
4. Well Location Unit Letter (C) D : 990 feet from the SOUTH line and 1650 feet from the EAST line Section 28 Township 18 S Range 34 E NMPM County LEA	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 4019.8' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: ADD PERFORATIONS <input checked="" type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Harvey E. Yates Company proposes to do as follows:

1. POOH w/rods and tubing.
2. Set CIBP @ 5860' ± with 50' cement on top.
3. GIH w/tbg to 4900', roll hole with 2% KCL subs.
4. Spot 200 gals 15% NEFE HCL acid. POOH.
5. Perforate Penrose @ 4858-4862' w/2 jspf.
6. GIH w/packer (with by-pass) and swab test perms.
7. May acidize with 1000/1500 gals same acid & b.s.
8. May fracture stimulate.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jeanetta Atkinson TITLE Production Analyst DATE 11/21/02

Type or print name Jeanetta Atkinson Telephone No. 505-623-6601

(This space for State use)

APPROVED BY GARY W. WINK TITLE STAFF MANAGER

Conditions of approval, if any:

ORIGINAL SIGNED BY

GARY W. WINK

OC FIELD REPRESENTATIVE

NOV 25 2002