

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

OIL CONSERVATION DIVISION

P. O. Box 2088

Santa Fe, New Mexico 87504-2088

DISTRICT I

P. O. Box 1980 Hobbs, NM 88240

DISTRICT II

P. O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd, Aztec, NM 87410

Well API NO. 30-025-32234

5. Indicate Type or Lease  
STATE  FEE

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name  
SANTA FE EXPLORATION

8. Well No. 2

9. Pool name or Wildcat  
UNDESIGNATED WILDCAT  
*S Carbon Wolfcamp*

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well  
OIL WELL  GAS WELL  OTHER  STILL TESTING

2. Name of Operator  
Harvey E. Yates Company

3. Address of Operator  
P.O. Box 1993, Roswell, NM 88202 1-505-623-6601

4. Well Location  
Unit Letter I : 1,980 Feet From The SOUTH Line and 660 Feet From The EAST Line

Section 6 Township 18-S Range 33-E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3964.9' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:  
PERFORM REMEDIAL WORK   
TEMPORARILY ABANDON   
PULL OR ALTER CASING   
OTHER:

SUBSEQUENT REPORT OF:  
REMEDIAL WORK   
COMMENCE DRILLING OPNS.   
CASING TEST AND CEMENT JOB   
OTHER: UPDATE ON ACTIVITY SINCE TD

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103

DRILL OUT DV & DOWN TO FLOAT COLLAR. RAN GRICCLACBL FROM 11432' TO 1200'  
12-7-93 PERF WOLFCAMP 11185-11248' & ACDZ w/ 750 GALS 20% NEFE. 12-9-93 SET CMT RET.  
AT 11165' & SQZ w/25 & 50 SKS CL H w/ FL. DRLD OUT & TEST TO 3000#; LOST 150 # IN 15 MIN.  
12-12-93 SAND JET 2 CUTS @ 11221 & 11216' & WASH EACH w/ 500 GALS 20%. 12-17-93 RE-ACDZ w/ 5000 GALS 20% NEFE &  
3500 GALS OVERFLUSH. 12-22-93 DUMP 1.25 SKS CMT ON TOP OF HUNG UP CMT RET @ 11243'. 12-23-93 TAG CMT @ 11235'  
w/ GUNS & PERF 11210-11224 ( 56 HOLES). ACDZ w/ 3000 GALS 20% NEFE. 12-28-93 REACDZ w/ 6000 GALS 20% & 4000  
GALS OF. 12-31-93 REACDZ w/ 25000 GALS 15% NEFE w/ .5 HF. 1-5-94 PERF WOLFCAMP 10810-11270 (70 HOLES). ACDZ w/  
3000 GALS 20% NEFE. 1-8-94 RE-ACDZ w/ 7500 GALS 20% & 4000 GALS OF. 1-12-94 SET CIBP @ TOP OF WOLFCAMP PER  
OCD I APPROVAL ON 1-11-94. SET AT 9654' PLUS 35' CMT. (NEW PBD=9619'). 1-11-94 PERF 9276-88 (24 HOLES) BONE SPRING  
ACDZ w/ 200 GALS 15%. 1-15-94 SET CIBP @ 9225' PLUS 45' CMT. (NEW PBD @ 9180'). 1-15-94 PERF DELAWARE 6448-60' 4602'  
(25 HOLES). ACDZ w/ 1500 GALS 15% NEFE. 1-20-94 FRAC w/ 20K GALS & 22K #'s 16-30 OTTAWA. 1-21-94 PUT ON JET PMP w/  
PKR @ 6267' TO TEST PRODUCTION FROM DELAWARE.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Ray F. Nokes* TITLE PROD. MGR. / ENGINEER. Date 2/8/94  
TYPE OR PRINT NAME RAY F. NOKES TELEPHONE NO. 1-505-623-6601

(This space for State use)

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

FEB 10 1994

Approved by \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_  
Conditions of approval, if any: \_\_\_\_\_