Submit 3 Copies to Appropriate

CONDITIONS OF APPROVAL, IF ANY:

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office		•	•	ivised 1 1 07
DISTRICT I P.O. Box 1980, Hobbs NM 88241-1980	OIL CONSERVATIO		WELL API NO.	
	2040 Pacheco St.		30-025-33659	
P.O. Drawer DD, Artesia, NM 88210	Santa Fe, NM 8	37505	5. Indicate Type of Lease STATE	X FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.	TEL CO
SUNDRY NOTICES AND REPORTS ON WELLS				
(DO NOT USE THIS FORM FOR PRO DIFFERENT RESER	M FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A ENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name S11verstrand State	
1. Type of Well: OIL GAS WELL WELL	OTHER			
2. Name of Operator			8. Well No.	
Marathon 011 Company			1	
3. Address of Operator P.O. Box 2409, Hobbs, NM 88	240		9. Pool name or Wildcat  Vacuum: Abo, North	
4. Well Location		404		
Unit Letter C : 660	Feet From The North	Line and 198	Feet From The	West Line
Section 2	10. Elevation (Show whether	er DF, RKB, RT, GR, etc	NMPM Lea	County
		4049' KB 4068'		
11. Check App	propriate Box to Indicate l	Nature of Notice,	Report, or Other Dat	a
NOTICE OF IN	ITENTION TO:	SUE	SEQUENT REPOR	IT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING O	CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. D PLUG AND A	ABANDONMENT
PULL OR ALTER CASING		CASING TEST AND CE		
OTHER:		OTHER: DO CIBP.	Test Wolfcamp/Abo for p	ossible DHC
12. Describe Proposed or Completed Ope work) SEE RULE 1103.				
5/6 MIRU PU. POOH w/pum Drill on plug. Push Load & test. OK. 5/11 RD PU.	p & rods. ND wellhead. NU into 11,000'. POOH. RIH w/2	BOPE. RIH & tag PB 7/8" tbg. ND BOP.	TD (CIBP) at 8950'. PO Set TAC. RIH w/pump &	OH. RIH w/bit. rods.
NOTE: No incremental in	crease in production from	the Wolfcamp forma	tion. Produced only wa	ter. Set CIBP.
6/27 RIH w/CIBP, set at	up & rods. ND wellhead. Rel 8950'. RIH w/pkr. set at 89 Set TAC. NU wellhead.	TAC. NU BOP. POOH 940'. Load & test.	w/2 7/8" tbg. OK. Rel pkr, POOH. RI	H w/2 7/8"
The share of the state of the s	rue and complete to the heat of our branch-de-	e and helief		
I hereby certify that the information above is to	n (a	e and belief. LE <u>Records Process</u>	ior sum	8/28/98
SIGNATURE JOHN	TIT	LE NECULUS FIUCESS	TELEPHONE NO	
TYPE OR PRINT NAME Kelly Cook			1 ELEFHORE IN	o. <u>393-7106</u>
(This space for State Use)  Concerns to the control of the control	Seption and Characterisms.			3
APPROVED BY	18.01 Children JA TIT	LE	DATE	