

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill-stem tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

[illegible]

38. GEOLOGICAL MARKERS			38. GEOLOGICAL MARKERS		
NAME	TOP		NAME	TOP	
	MEAS. DEPTH	TRUE VERT. DEPTH		MEAS. DEPTH	TRUE VERT. DEPTH
Rustler	1340		Morrow	12676	
Yates	3044				
Queen	4166				
Penrose	4382				
Delaware	5406				
Bone spring	7288				
Wolfcamp	10614				
Penn Shale	11316				
Strawn	11893				
Atoka	12349				

