

COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REWORK OR PLUG WELLS TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL (C-101) FOR SUCH PROPOSALS.)		5a. Indicate Type of Lease State ☒ Fee ☐
5. State Oil & Gas Lease No. B-2317		7. Unit Agreement Name
6. Name of Operator Atlantic Richfield Company		
7. Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240		8. Form or Lease Name State Vacuum Unit
8. Location of Well UNIT LETTER A 990 FEET FROM THE North LINE AND 330 FEET FROM THE East LINE, SECTION 31 TOWNSHIP 17S RANGE 34E N.M.P.M.		9. Well No. 2
10. Field and Pool, or Wildcat Vacuum Grbg SA		12. County Lea
11. Elevation (Show whether DF, RT, GR, etc.) 4080.5' GR		

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER Side track junk in hole ☒	SUBSEQUENT REPORT OF: PLUG AND ABANDON ☐ CHANGE PLANS ☐ REMEDIAL WORK ☐ COMMENCE DRILLING OPNS. ☐ CASING TEST AND CEMENT JOBS ☐ OTHER ☐ ALTERING CASING ☐ PLUG AND ABANDONMENT ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 4739'

8-5/8" csg set @ 1550' & cmt'd w/500 sx.

5-1/2" OD csg set @ 4652' & cmt'd w/100 sx.

This well has fish stuck in hole from 3784-4701.75' KB. Propose to sidetrack fish in the following manner:

- GIH w/tbg to top of fish @ 3784'. Pump 10 BFW followed by 70 sx Cl C cmt cont'g 4% gel, flush w/4 BW. POH w/tbg.
- Cut & pull 5 1/2" csg from 3784'.
- GIH w/tbg & spot 300' side track plug using Cl H cmt cont'g 1% CFR-2, 5.25#/sk salt & 5#/sk sd.
- GIH w/7-7/8" bit & dress top cmt plug using saturated salt gel mud.
- Run bent sub & dyna-drill, side track 5 1/2" csg & drill to 4750' TD, near old hole as possible.
- Run 5 1/2" OD 17# J-55 or 4 1/2" OD 9.5# J-55 csg as determined by condition of 5 1/2" csg pulled. Run DV tool @ 3800', csg to 4750', cmt csg to surf. Leave well shut in. To be converted to WIW.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Dist. Drlg. Supt. DATE 3/21/77

REMOVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: