

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-02904
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1839

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name East Vacuum Gb/SA Unit Tract 2738
2. Name of Operator Phillips Petroleum Company	8. Well No. 002
3. Address of Operator 4001 Penbrook Street, Odessa, Texas 79762	9. Pool name or Wildcat Vacuum Gb/SA
4. Well Location Unit Letter <u>F</u> : <u>1980</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>West</u> Line Section <u>27</u> Township <u>17-S</u> Range <u>35-E</u> NMPM <u>Lea</u> County <u></u>	
10. Elevation (Show whether DP, RKB, RT, GR, etc.) <u>3938' GR</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Clean out and stimulate ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-10-92: COOH w/2-7/8" tbq. GIH w/500' tailpipe, pkr, & tbq. With tailpipe @ +4600' and pkr @ +4100' pkr would not set. COOH & change pkr. GIH w/ tailpipe @ +4600'. Pump 20 bbl 2% KCl w/10 gal Techni-Wet 425 and 1/2 of 495 gal Techni-Clean 405 and 495 gal mix. Set pkr @ 3706' and tail pipe @ 4211'. Wait 3 hrs. - displace rest of mix and flush tbq.
4-13-92: Pump 4500 gal 15% NEFe HCl acid. Swab.
4-14-92: COOH w/tbq. LD pkr. GIH w/sub equip and tbq. Start pumping.
4-18-92: Pump 24 hrs. 71 BOPD 722 BWPD 395 MCFD 5534.538 GOR.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. M. Sanders TITLE Supv., Reg. & Proration DATE 04-24-92
TYPE OR PRINT NAME L. M. Sanders TELEPHONE NO. (915) 368-1488

(This space for State Use)

ORIGINAL SIGNED BY RAY SMITH
FIELD REP. II

APR 29 '92

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 28 1992

OCD HOBBS OFFICE