

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1940, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.  
30-025-23410

5. Indicate Type of Lease  
STATE  FEE

6. State Oil & Gas Lease No.  
L-200

7. Lease Name or Unit Agreement Name

State DS

8. Well No.

6

9. Pool name or Wildcat

Spencer San Andres

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
oil well  gas well  other

2. Name of Operator  
Mack Energy Corporation

3. Address of Operator  
P.O. Box 960, Artesia, NM 88211-0960

4. Well Location  
Unit Letter 0 : 990 Feet From The South Line and 2310 Feet From The East Line  
Section 24 Township 17-S Range 36-E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3801'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK  PLUG AND ABANDON   
TEMPORARILY ABANDON  CHANGE PLANS   
PULL OR ALTER CASING   
OTHER:

SUBSEQUENT REPORT OF:

REMEDIAL WORK  ALTERING CASING   
COMMENCE DRILLING OPNS.  PLUG AND ABANDONMENT   
CASING TEST AND CEMENT JOB   
OTHER:

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-11-02 Rig up unit, RIH w/ CIBP, set down @ 4319', run drill bit & clean out hole.  
10-14-02 Set 5-1/2" CIBP @ 4840' cap w/ 35', mud up hole. Pressure test csg. @ 600 PSI (didn't hole), perf. 4 holes @ 1970', sqz 35 sx cmt. WOC.  
10-15-02 Tag cmt. plug @ 1850', perf. 4 holes @ 382', sqz 35 sx w/ 2% CaCl. WOC & tag cmt. plug @ 278', spot 10 sx cmt. to surface 60' - 3'.  
Rig down unit, & move off location. Clean location, cut off wellhead & install dry hole marker.

Approved as to plugging of the Well Bore.  
Liability under bond is retained until  
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Lisa D. Cat TITLE Production Analyst DATE 10/21/2002

TYPE OR PRINT NAME TELEPHONE NO.

(This space for State Use)  
GARY W. WINK  
OC FIELD REPRESENTATIVE II/STAFF MANAGER

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

GWU

JAN 22 2003

3

1. The first part of the document is a list of the names of the members of the committee who have been appointed to study the problem of the shortage of housing in the city of New York.

2. The second part of the document is a list of the names of the members of the committee who have been appointed to study the problem of the shortage of housing in the city of New York.