

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-3454	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input checked="" type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER <input type="checkbox"/>
Name of Operator GULF OIL CORPORATION		
Address of Operator P.O. Box 670, Hobbs, NM 88240		
Location of Well UNIT LETTER <u>D</u> <u>770</u> FEET FROM THE <u>North</u> LINE AND <u>560</u> FEET FROM THE <u>West</u> LINE, SECTION <u>36</u> TOWNSHIP <u>19S</u> RANGE <u>34E</u> NMPM.		

7. Unit Agreement Name
8. Farm or Lease Name Lea "DS" State
9. Well No. 2
10. Field and Pool, or Wildcat Bone Springs
12. County Lea

15. Elevation (Show whether DF, RT, GR, etc.)
3723' GL

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

1. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9770' TD. POH w/tbg. Set CIBP @ 9375'. Circulate abandonment mud. Test csg to 500#. Cap CIBP w/35' cmt. Spot 100' plug @ 5400'-5300'. Spot 200' cmt plug @ 2350'-2150'. Spot 100' cmt plugs @ 1950'-1850'; & 400'-300'. Spot 50' surface plug. Clean & clear location.

THIS CERTIFICATE MUST BE NOTICED 24
HOURS BEFORE THE BEGINNING OF
THE WORK TO BE DONE AND MUST BE
FILED IN THE OFFICE OF THE
COMMISSIONER OF THE NEW MEXICO
ENERGY AND MINERALS DEPARTMENT.

2. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>N. B. Sikes, Jr.</u>	TITLE <u>Area Engineer</u>	DATE <u>1-31-80</u>
PROVED BY <u>Jerry Clatter</u>	TITLE <u></u>	DATE <u></u>
CONDITIONS OF APPROVAL, IF ANY:		

FEB 1 1980