

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
L-3776	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Steve Sell		8. Farm or Lease Name Marathon State
3. Address of Operator P. O. Box 5061, Midland, Texas 79704		9. Well No. #1
4. Location of Well UNIT LETTER M 330 FEET FROM THE South LINE AND 330 FEET FROM West LINE, SECTION 18 TOWNSHIP 17S RANGE 34E N.M.P.M.		10. Field and Pool, or Wildcat Vacuum AB-SA
15. Elevation (Show whether DF, RT, GR, etc.) 4120 Grd.		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to plug and abandon the above according to the following:

Set CIBP at 3750'. Dump 35' of cement on top of CIBP. Circulate hole with 9.5# brine with 25# of salt gel per barrel. Set 100' plug - 2650-2550'. Spot 100' plug - 1616-1416'. Spot 100' plug 450-350'. Spot 10 sx. surface plug and install marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Chuck Morgan TITLE Agent DATE 12-11-86
APPROVED BY Chuck Morgan ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR DATE DEC 22 1986
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

DEC 22 1986

**OCD
HOBBS OFFICE**