Submit 3 Copies to Appropriate District Office

CONDITIONS OF APPROVAL, IF ANY:

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office			
DISTRICT I P.O. Box 1980, Hobbs NM 88240	OIL CONSERVATIO		WELL API NO.
DISTRICT II	P.O. Box 2088 Santa Fe, New Mexico 87504-2088		30-025-27418 5. Indicate Type of Lease
P.O. Drawer DD, Artesia, NM 8/10			STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS			K-6023-1
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name of Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			EAST VACUUM GB/SA UNIT
1. Type of Well:	· · · · · · · · · · · · · · · · · · ·		TRACT 1881
OIL WELL WELL	OTHER		1.0.0.
2. Name of Operator			8. Well No.
Phillips Petroleum Company 3. Address of Operator			9. Pool name or Wildcat
4001 Penbrook Street, Odessa, TX 79762			VACUUM GB/SA
4. Well Location Unit Letter N . 660) Feet From The SOUTH	Line and 23	10 Feet From The WEST Line
Unit Letter R: 000	J Feet From The SUUIN	Line and23	Feet From The WEST Line
Section 18	Township 17 SV Rs		NMPM LEA County
	10. Elevation (Show whether	er DF, RKB, RT, GR, etc 3994'GR	c.)
11. Check Au	opropriate Box to Indicate		Report, or Other Data
-	NTENTION TO:	1	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON X	REMEDIAL WORK	☐ ALTERING CASING ☐
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS. L PLUG AND ABANDONMENT L
PULL OR ALTER CASING CASING TEST AND CE			MENT JOB
OTHER:	П	OTHER:	П
 Describe Proposed or Completed Opwork) SEE RULE 1103. 	erations (Clearly state all pertinent det	ails, and give pertinent da	tes, including estimated date of starting any proposed
	/ DOWN EQUIPMENT. SET	5-1/2" CIBP AT	4620'. CIRCULATE CSG
W/9.5 MUD-LADEN FLU 2. SPOT PLUG NO. 1 (29	5 SX CMT) 4620'-4520'.	COVERS THE SAN	ANDRES.
	5 SX CMT) 4346'-4246'.	COVERS THE GRA	
4. SPOT PLUG NO. 3 (25	5 SX CMT) 3066'-2966'.	COVERS THE YAT	ES.
5. SPOT PLUG NO. 4 (25 SX CMT) 1850'-1750'. COVERS THE CASING SHOE AND SALT TOP.			
6. SPOT PLUG NO. 5 (50 SX CMT) 435'-3'. 7. CUT OFF CASING 3' BELOW GROUND LEVEL. INSTALL MONUMENT MARKER. PERFORM RECLAMATION WORK.			
7. COI OFF CASING 3 DELOW GROUND LEVEL. INSTALL HUNORILM HARREN. FERTURA RECEMBATION WORK			
I hereby certify that the information above is	true and complete to the best of my knowledg	e and belief.	
SIGNATURE SIGNATURE	inles III	TE SUPERVISOR F	REG. AFFAIRS DATE 3/3/95
		- ADILINE SAME	
TYPE OR PRINT NAME M. SANDE	RS		TELEPHONE NO.915/368-1488
(This space for State Use)	Orig. Signed by		MAD OF ASSE
	Paul Kautz Geologist		MAR 07 1995
APPROVED BY	_	LE	DATE