Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

OIL CONSERVATION DIVISION

OIL CONSERVATION DIVISION O. Box 1980, Hobbs, NM 88240 P.O. Box 2088			WELL API NO. 30-025-31373	
STRICT II D. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088			5. Indicate Type of Lease STATE X FEE	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No. E-1190	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name	
. Type of Well: OIL OAS WELL OTHER P&A			Little Maggie AJN State	
2 Name of Operator YATES PETROLEUM CORPOR	RATION		8. Well No.	
3. Address of Operator			9. Pool name or Wildcat Young Strawn	
105 South 4th St., Art	esia, NM 88210		Today belawn	
4. Well Location Unit Letter \underline{I} : 231	O Feet From The South	Line and990	Feet From TheEast	Line
Section 16	Township 18S Rai		NMPM Lea Cou	unty
	10. Elevation (Show whether I			
//////////////////////////////////////	Appropriate Box to Indicate N		leport, or Other Data	
	NOTICE OF INTENTION TO:		SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON (XX)	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	G OPNS. PLUG AND ABANDONME	.NT L
PULL OR ALTER CASING		CASING TEST AND C	EMENT JOB	
OTHER:		OTHER:		
work) SEE RULE 1103. 1-27-93. Procedure v NMOCD 24 HRS ADVANCE that YPC will reenter approved. (Pull casin RBP's are still in ho casing w/9.0 ppg BW w casing w/mud from 108 7150' Bone Spring, 58 Option 1: With well casing. Spot 65 sx c 405-305'. Spot 10 sx Option 2: Shoot 4 sq rate and pump 55 sx c C cement down 5½" and from surface to 405'. Thereby certify that the information above is	erbally approved by Paul NOTICE OF PLUGGING (HOB) this well to test the g, leave casing in hole le, TIH and pull RBP's. /25#/bbl salt gel (250 00'. TOOH. Set CIBP w/3. 25' Delaware, 4525' Low loaded w/fluid and dead ement plug from 3050-28 cement plug 40' to sur ueeze holes at 3000' an ement. Sting out and rup the 8-5/8"x5½" annu Install dry hole mark	1 Kautz, NMOCD, BS, 393-6161). Queen in 3900'). PROCEDURE. RIH to 10800' bbl casing capa 5' cement at foington Sand., shoot off 5-175'. WOC. Tag face. Install d 405'. Set reeverse circulat lus so that caser.	te tubing clean. TOH. Pump I sing and annulus are full of	ns are BOP. If rculate hole, fill fcamp, down ig from njection 100 sx Clas
SIGNATURE LU anita	Carditt II	TLE Production S	Supervisor pate	
TYPE OR PRINT NAME Juani	ta Goodlett		TELEPHONE NO. 505/	748-1471 ———
(This space for State Use)	and of heary sexyem on toursevisor	TLE	DATE FEB 03	1993

TITLE -

APPROVED BY -