

L. P. Thompson
Division Manager
Production Department
Hobbs Division

Western Hemisphere Petroleum Division
Continental Oil Company
P.O. Box 460
1001 North Turser
Hobbs, New Hemisphere Petroleum Division
Continental Oil Company
P.O. Box 460
1001 North Turser
Hobbs, New Hemisphere Petroleum Division
Continental Oil Company
P.O. Box 460
1001 North Turser
Hobbs, New Hemisphere Petroleum Division
Continental Oil Company
P.O. Box 460
1001 North Turser
Hobbs, New Hemisphere Petroleum Division
Continental Oil Company
P.O. Box 460
1001 North Turser
Hobbs, New Hemisphere Petroleum Division
Continental Oil Company
P.O. Box 460
1001 North Turser
Hobbs, New Hemisphere Petroleum Division
Continental Oil Company
P.O. Box 460
1001 North Turser
Hobbs, New Hemisphere Petroleum Division
Continental Oil Company
P.O. Box 460
1001 North Turser
Hobbs, New Hemisphere Petroleum Division
Continental Oil Company
P.O. Box 460
1001 North Turser
Hobbs, New Hemisphere Petroleum Division
Continental Oil Company
P.O. Box 460
1001 North Turser
Hobbs, New Hemisphere Petroleum Division
Continental Oil Company
P.O. Box 460
1001 North Turser
Hobbs, New Hemisphere Petroleum Division
Continental Oil Company
P.O. Box 460
1001 North Turser
Hobbs, New Hemisphere Petroleum Division
Continental Oil Company
P.O. Box 460
1001 North Turser
Hobbs (1001 North Turser)
Hobbs (1001 North Tur

1 1972

OIL CONSERVATION COMM. HOBES, N. M.

October 26, 1972

Mr. Joe D. Ramey New Mexico Oil Conservation Commission P. O. Box 1980 Hobbs, NM 88240

Dear Mr. Ramey:

Sanderson B-1 No. 2, Unit H, Section 10, T-20S, R-36E, Lea County, New Mexico

The subject well is a dual completion in the Eumont Gas Pool (upper completion) and the Monument Oil Pool (lower zone). Oil production from the Monument Pool had dropped to a sub-commercial rate and it was abandoned but not permanently plugged with a tubing bridge plug. A diagram of the well is attached, and Form 9-331 is being submitted to the USGS with information copy to you.

It is requested that the well be exempted from the requirement of packer leakage tests. Due to the mechanical condition, it is impossible to take a meaningful test.

Thank you.

Very truly yours,

Thenpero

L. P. Thompson

jll + enc.
CC: VTL WDH