

NO. OF COPIES RECEIVED	
DISTRIBUTION	
DATE	
FILE	
S.G.S.	
AND OFFICE	
PERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REPER OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		50. Indicate Type of Lease State ☐ Fee ☒
5. State Oil & Gas Lease No.		
7. Unit Agreement Name		
8. Farm or Lease Name L. W. White (NCT-B) Tr A		
9. Well No. 4		
10. Field and Pool, or Wildcat Eumont		
11. Elevation (Show whether DF, RT, GR, etc.) 3560' GL		
12. County Lea		

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
REPER OR ALTER CASING ☐	OTHER Plug and abandon. ☐	CASING TEST AND CEMENT JOB ☐	OTHER ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3850' TD.
Pull producing equipment. Set CI BP at 3675' and cap with 8 sacks, 41' of cement to 3634', abandoning open hole interval 3725' to 3850'. Load hole with abandonment mud. Spot 10 sack cement plug from 51' to surface. Install dry hole marker and clean location.

* (2) If production cgs. is not cut & pulled, 7" cgs must be perforated at 390', and plug squeezed behind same

(b) If 7" production cgs. is cut & pulled a 100' plug in & out stub is required

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

BY <u>D. F. Berlin</u>	TITLE <u>Area Engineer</u>	DATE <u>September 16, 1976</u>
APPROVED BY <u>John W. Runyan</u>	TITLE <u>Geologist</u>	DATE <u>SEP 14 1976</u>

CONDITIONS OF APPROVAL, IF ANY:

note above