

(SUBMIT IN TRIPLICATE)

UNITED STATES

Land Office Leaf Cricos

Lease No. 031670 (a)

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY		Unit. N.M.F.U.
		RECEIVED
SUNDRY NOTICES A	AND REPORTS ON	SEP 17 1951 WELLS
NOTICE OF INTENTION TO DRILL	CURSEOUTH	OIL CONSERVATION COMMISSION
NOTICE OF INTENTION TO CHANGE BLANC	THE STATE OF WALER SE	TUT-OFF HOBBS-CT
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		OR ACIDIZING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	THE THE SET OF ALTERING	CASING
NOTICE OF INTENTION TO SHOOT OR ACIDIZE NOTICE OF INTENTION TO PULL OR ALTER CASING	SUBSEQUENT REPORT OF REDRILLIP	NG OR REPAIR
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUBSEQUENT REPORT OF ABANDONI	MENT
	Report of Fire	
(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)		
SEND-Burger A-19 Bo, 9 Hobbs, New Memiles September 14, 19 51		
Well No. 9 is located 3980 ft. from line and 1980 ft. from E line of sec. 19		
MR/I 9 4		('-)
HE/4 Sec. 19 (1 Sec. No.) (Twp.)	(Range) (Meridian)	
Skages (Field)		
(Field) (County of	or Subdivision)	
The elevation of the derrick floor above sea level isft.		
ft.		
DETAILS OF WORK		
(State names of and expected depths to objective and a share to	25 OF WURK	
(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)		
On August 10, 1951, while at a depth of 3695! in lies, drilling contractor attempted to run caliper survey in subject well, but was mable to reach bottom. Drill pipe with bit was run and bridge at approximately 900: was being drilled when the well blew out and caught on fire. It is estimated that approximately 600 MCF gas was consumed during this fire which lasted about eight hours. No oil was being produced at the time. There were no personal injuries in connection with this fire. The drilling contractor's rig was badly damaged and was replaced with another rig. Orilling of bridge at 920: was resumed and resulted in side-tracking old hole. Drilling operations are now in progress in new hole at depth of 3420!		
I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.		
Company Company		
Address See CC	•	
Hobbie, Roy Esseries	By	Supra
	Title Ass. Mat.	Supto

U. S. GOVERNMENT PRINTING OFFICE

Principles of the second of th

ger og fel safrækki