

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT, NEW MEX

SUBMIT IN TRIPL
(Other instructions
reverse side.)

Budget Bureau No. 1004-0135
Expires August 31, 1985
LEASE DESIGNATION AND SERIAL NO.

LC-031670(B)

IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Injection Shut-in	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR CONOCO INC.	8. FARM OR LEASE NAME SEMU Permian
3. ADDRESS OF OPERATOR P. O. Box 460, Hobbs, N.M. 88240	9. WELL NO. 49
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit E	10. FIELD AND POOL, OR WILDCAT Skaggs Grayburg
11. PERMIT NO. 1980' FNL & 660' FNL 30-025-07828	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 20-20S-38E
12. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH Lea
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☒
(Other) ☐	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE DRILLING OR COMPLETED OPERATIONS. Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.

- ① MIRU on 8-5-86. Tag top of fish @ 2348'. Set magnet on top of fish, POOH w/ small pieces of junk metal. RIH w/ flat bottom mill. Tag top of fish @ 2348'. Mill fish & junk to 2367', broke free.
- ② Wash scale off csg, circ. hole clean. Mill over fish from 2381' to 243'. Had 57' junk tbg in wash pipe. Mill over fish to 2660'.
- ③ Ran scraper to 2645'. Set cmt retainer @ 2604'. Pumped 165 sxs class "c" thru retainer into formation. Spot 10 sxs cmt on retainer.
- ④ Found bad csg from 1543'-2560'. RIH w/ open ended tbg to 2570'. Spot 115 sxs class "c" over interval 1435'-2570'. Set cmt ret @ 1057'. Pumped 128 sxs class "c" & circ. 25 sxs to surface. Top off wellbore w/cm
- ⑤ Cut off wellhead. Dug out cellar & installed P&A marker. Rig down on 8-14-86.

I hereby certify that the foregoing is true and correct

Signed by <i>Rajendra Giri</i>	TITLE Administrative Supervisor	DATE 9-22-86
Signed by <i>Rajendra Giri</i>	TITLE AREA MANAGER CARLSBAD RESOURCE AREA	DATE 6-10-87

*See Instructions on Reverse Side

Whoever makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM-Carlsbad (6) ARCO (2) AMOCO (2) Chevron (1) File

RECEIVED
JUN 11 1997
OCD
HOBBS OFFICE