

30-025-07872

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

## NEW MEXICO OIL CONSERVATION COMMISSION

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>K-5563</b>	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Re-entry</b>		7. Unit Agreement Name -----
2. Name of Operator <b>Morris R. Antweil</b>		8. Farm or Lease Name <b>Lea <del>3000</del> "BU"</b>
3. Address of Operator <b>Box 2010, Hobbs, New Mexico 88240</b>		9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>C</b> <b>330</b> FEET FROM THE <b>North</b> LINE AND <b>2307</b> FEET FROM THE <b>West</b> LINE, SECTION <b>32</b> TOWNSHIP <b>20S</b> RANGE <b>38 E</b> NMPM.		10. Field and Pool, or Wildcat <b>Wildcat</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3523' DF</b>		12. County <b>Lea</b>

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐PLUG AND ABANDON ☐REMEDIAL WORK ☐ALTERING CASING ☐TEMPORARILY ABANDON ☐COMMENCE DRILLING OPNS. ☐PLUG AND ABANDONMENT ☒PULL OR ALTER CASING ☐CHANGE PLANS ☐CASING TEST AND CEMENT JOB ☐OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well was abandoned as follows:

- (1.) Loaded hole with heavy mud.
- (2.) Spotted 25 sx. cement plug at 6500'-6700'.
- (3.) Spotted 20 sx. cement plug 6275' --6450'.
- (4.) Spotted 35 sx. cement plug 5975' - 6250'.
- (5.) Shot 5-1/2" casing @ 3500', pulled and recovered 3497' 5-1/2" csg.
- (6.) Spotted 20 sx. cement plug across 5-1/2" csg. stub @ 3500'.
- (7.) Spotted 20 sx. cement plug across 8-5/8" csg. shoe @ 2991'.
- (8.) Spotted 10 sx. surface plug and erected marker.
- (9.) Cleaned location. Plugged and Abandoned 4-4-68

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Rm WilliamsTITLE AgentDATE 4-9-68APPROVED BY John W. Runyan

TITLE

DATE

CONDITION OF APPROVAL, IF ANY: