

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-11223-2	

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Water Injection Well		7. Unit Agreement Name Cone Jalmat Yates Pool Unit
2. Name of Operator J.R. Cone		8. Farm or Lease Name Tract 1
3. Address of Operator Box 10217, Lubbock, TX 79408		9. Well No. 4
4. Location of Well UNIT LETTER J, 1980 FEET FROM THE South LINE AND 1980 FEET FROM East THE East LINE, SECTION 13 TOWNSHIP 22-S RANGE 35-E NMPM.		10. Field and Pool, or Wildcat Jalmat
15. Elevation (Show whether DF, RT, CR, etc.) 3599 DF (datum); 3594 THF		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Basic mechanical data: TD4002'-7-7/8" hole. PBDT 3963' (June 1955). 5½ csg cem. @ 4002' w/800 sx. Csg perf'd w/6 bullets/ft: 3663-67; 3676-96; 3710-74; 3790-3806 and 3830-3840'; also jet perf'd 3862-78 w/2 SPF; 3898-3902 & 3922-26' w/3 SPF. Well converted to water injection July 1963,

January 30, 1986: Set 5½ CIBP @3550. Spot 4 sx 3550 to 3510. Pull up hole to 3500 and circulate hole with mud. Spot 15 sx 1678 to 1547. Perf @320 and set packer @120'; Mix 40 sx and displace to 250'. Tested to 500# and tag cement at 238. Mix 10 sx surf plug and install marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>James R. Cone, Jr.</u>	TITLE <u>Agent</u>	DATE <u>12-29-86</u>
APPROVED BY <u>Paul E. Turnachoff</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>10-1-86</u>
CONDITIONS OF APPROVAL, IF ANY:		

8