

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS
(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY E. P. CAMPBELL, 902 Lubbock National Bank Bldg., Lubbock, Texas
(Address)

LEASE State (Sehermerhorn) WELL NO. 1 UNIT P S 36 T 22 South R 35 East
DATE WORK PERFORMED 11-7-58 POOL Jalmat

This is a Report of: (Check appropriate block) ☐ Results of Test of Casing Shut-off
☒ Beginning Drilling Operations ☐ Remedial Work
☐ Plugging ☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

Spud 11-6-58

Set 8 5/8" casing @ 200 feet w/150 sacks regular neat cement.
Circulated 50 sacks.

Pressured up 750#, pressure held on casing 24 hours, no drop in pressure.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____
Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____
Perf Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

BEFORE

AFTER

Date of Test

Oil Production, bbls. per day

Gas Production, Mcf per day

Water Production, bbls. per day

Gas-Oil Ratio, cu. ft. per bbl.

Gas Well Potential, Mcf per day

Witnessed by _____

(Company)

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name John W. Runyan

Name John W. Runyan

Title _____

Position Geologist

Date _____

Company E. P. Campbell

902 Lubbock National Bank Building
Lubbock, Texas