

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPL
(Other instructions
reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR CONOCO INC.	8. FARM OR LEASE NAME Warren Unit
3. ADDRESS OF OPERATOR P. O. Box 460, Hobbs, N.M. 88240	9. WELL NO. 53
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit C 660' FNL & 1980' FWL	10. FIELD AND POOL, OR WILDCAT Blinebry Oil & Gas/Warren Tubl
14. PERMIT NO. 30-025-25916	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 26 - 20S - 38E
15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE Lea NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- ① An application to downhole commingle this well was filed w/ NMOCB on 10-1-86.
- ② MUR. POOH w/ rods & pump. POOH w/ both strings of tbg
- ③ Mill out pkr @ 6400' & POOH w/ pkr and mill. Clean out well to 6780'
- ④ Set RBP @ 6740' & pkr @ 6450'. Acidize Tubb perms w/ 45 bbls 75% HCL/25% xylene mix and flush w/ 48 bbls TFW. Swab. Reset RBP @ 6450' & pkr @ 580'
- ⑤ Acidize Blinebry perms w/ 63 bbls 75% HCL/25% Xylene mix and flush w/ 37 bbls TFW. Swab back load. POOH w/ RBP & pkr.
- ⑥ GIH w/ prod. equipment. Land tbg @ 6710' & rig down.
- ⑦ A well sketch is attached.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Administrative Supervisor

DATE

10-2-86

(This space for Federal or State office use)

Orig. Use

APPROVED BY

TITLE

DATE

10-16-86

CONDITIONS OF APPROVAL, IF ANY:

Subject to
Like Approval

*See Instructions on Reverse Side

Section 15 of the Federal Land Management Policy Act of 1981, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM - Carlsbad (6) ARCO (2) AMOCO (2) File (1) Chevron (1)

RECEIVED
OCT 20 1986
O.C.D.
HOBBS OFFICE