

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State  Fee   
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL  GAS WELL  OTHER   
2. Name of Operator: Conoco Inc.  
3. Address of Operator: P.O. Box 460 - Hobbs, New Mexico 88240  
4. Location of Well: UNIT LETTER P, 510 FEET FROM THE South LINE AND 810 FEET FROM THE east LINE, SECTION 21 TOWNSHIP 21S RANGE 37E N.M.P.M.  
7. Unit Agreement Name  
8. Farm or Lease Name: M.E. Wantz  
9. Well No.: 3  
10. Field and Pool, or Wildcat: Paddock  
15. Elevation (Show whether DF, RT, GR, etc.)  
12. County: Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK  PLUG AND ABANDON  REMEDIAL WORK  ALTERING CASING   
TEMPORARILY ABANDON  CHANGE PLANS  COMMENCE DRILLING OPNS.  PLUG AND ABANDONMENT   
PULL OR ALTER CASING  OTHER Perforate & Acidize Paddock  CASING TEST AND CEMENT JOBS   
OTHER \_\_\_\_\_

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) POOH w/ Paddock string rods, pump & Abq.
- 2) Clean wellbore to PDB at 5723'. Circ clean w/ 2% KCL TFW & POOH.
- 3) Log from 5500' to minimum footage. Perforate 5325-5110' w/ 2 1/2 spf & POOH.
- 4) RIT w/ 7" RBP, on-off tool, 7" Arty pka, SN & 2 7/8" workstring. Pressure test Abq to 5000 psi. Set RBP at 5445' & pka at 5010'. Pressure up on backside to 500 psi.
- 5) Acidize from 5110' - 5345' w/ 275 bbls 75% / 25% - 15% HCl-NE-FE & Xylene w/ 3 drums B5 Titan MAS or equivalent plus 800 lb graded rock salt in 3 bbls 10% gelled brine in 5 equal stages. Flush w/ 55 bbls 2% KCL TFW. Swab well. Release pka at 5010' & retrieve RBP at 5445' & POOH.
- 6) Set Abq anchor at 5270' & SN at 5360'. Rein producing equipment & place on production for further into contact James Hedrick at 397-5869

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED DF FINNEY TITLE Administrative Supervisor DATE October 7, 1958

APPROVED BY Paul Kautz ORIG. SIGNED BY Paul Kautz Geologist TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: \_\_\_\_\_

Wantz No. 3

510' FSL, 810' FEL  
Sec 21, T-21S, R-37E  
Lea County, NM

Proposed Wellbore Diagram

3430' GL  
12' ABL

