

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION, INC.

JUN 14 11 52 AM '67

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	State <input type="checkbox"/>	Fee <input type="checkbox"/>
----------------------------	--------------------------------	------------------------------

5. State Oil & Gas Lease No.

SJNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator M-T-A SUPPLY COMPANY	8. Farm or Lease Name WALLACE STATE
3. Address of Operator P. O. BOX 2070, HOBBS, NEW MEXICO 88240	9. Well No. 7
4. Location of Well UNIT LETTER <u>B</u> <u>5610</u> FEET FROM THE <u>SOUTH</u> LINE AND <u>330</u> FEET FROM THE <u>WEST</u> LINE, SECTION <u>3</u> TOWNSHIP <u>21-N</u> RANGE <u>36-E</u> NMPM.	10. Field and Pool, or Wildcat OIL CENTER
15. Elevation (Show whether DF, RT, GR, etc.)	12. County

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

PLUG AND ABANDON	<input type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK	<input checked="" type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
COMMENCE DRILLING OPNS.	<input type="checkbox"/>	PLUG AND ABANDONMENT	<input type="checkbox"/>
CASING TEST AND CEMENT JOB	<input type="checkbox"/>		
OTHER	<input type="checkbox"/>		

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Kill well with lease oil.
2. Rig up A-pert Well Service, pull tubing-went back in with Baker Full-bore set - 5760', tagged bottom - 5970'.
3. Acidize 1000 gals. 15% Spearhead acid, drop 30 balls in 4 stages, had 50% increase. Dropped balls and pushed off with Packer. Reset Packer - 5760' and acidized with 7,500 gals. 15% Reactrol - 5 B/W, 4100 PSI. Shut in and on vacuum in 30 minutes. All treatment through perfs 5380 to 5906. Pulled Baker Packer and ran 30' mud anchor, bull plugged 4' perforations, setting nipple--setting nipple at 5910'. Swabbed and flowed load. Max SICP 1100# SITP 450#
Test 137 BC on 24/64 choke CP 450 TP 150. No water. GOR 1471:1

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>R. L. Montgomery</u>	TITLE <u>AGENT</u>	DATE <u>6/13/67</u>
APPROVED BY <u>[Signature]</u>	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:		

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION
HOBBS OFFICE O.C.C.

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

JUN 2 11 37 AM '67

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Mo-Tex Supply Company	8. Farm or Lease Name allace State
3. Address of Operator P. O. Box 2070, Hobbs, New Mexico	9. Well No. #7
4. Location of Well UNIT LETTER E 5610 FEET FROM THE South LINE AND 330 FEET FROM THE West LINE, SECTION 3 TOWNSHIP 21-S RANGE 36-E NMPM.	10. Field and Pool, or Wildcat Oil Center Blinbry
15. Elevation (Show whether DF, RT, GR, etc.) 3523 GR	12. County

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Cut paraffin
2. Rig up 1-port well Service
3. Kill well with lease oil
4. Tag bottom PBTD 5944
5. Pull tubing and strap
6. Lay down perforation and setting nipple
Pick up Baker Full-bore cementor 2 3/8 cuex 4 1/2 11.60# J-55 two joints off bottom
7. Run tubing w/Packer below perfs 5880 to 5906 feet 2 JSPF 26 feet 52 holes.
8. Spot 250 gallons Spearhead Acid
9. Pickup tubing above 5850 feet, set Packer and pump 750 gallons Spearhead Acid with 60 ball sealers
10. Drop balls and acidize with 7,500 gallons 15% neatrol--shutin overnite
11. Pull Packer, rerun tubing with mud anchor ball plugged, perforation and setting nipple.
12. Subb to test tank.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R. L. Montgomery	TITLE Geologist	DATE 6-1-67
APPROVED BY Leslie J. Clements	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:		