Submit 3 Copies to Appropriate District Office

## State of New Mexico En ...., Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

VELL API NO		
30-025-10502		

P.O. Box 1980, Hobbs, NM 88240	310 Old Santa Fe Trail, Room 206		WELL API NO. 30-025-10502	
P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New	Mexico 87503	5. Indicate Type of Lease  STATE FEEXX	
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410			6. State Oil & Gas Lease No LC 058626-A	
( DO NOT USE THIS FORM FOR PR DIFFERENT RESE	ICES AND REPORTS ON OPOSALS TO DRILL OR TO DE RVOIR. USE "APPLICATION FO 101) FOR SUCH PROPOSALS	EPEN OR PLUG BACK TO A DR PERMIT"	7. Lease Name or Unit Agreement Name	
1. Type of Well: OIL GAS WELL XX WELL			LANGLIE-MATTIX PENROSE SAND UNIT TRACT 26	
Name of Operator     ANADARKO PETROLEUM COF			8. Well No. 01	
3. Address of Operator P.O. BOX 2497, MIDLAND, TX 7	9702		Pool name or Wildcat     LANGLIE-MATTIX SR ON GRBG	
Well Location     Unit Letter G 23	10 Feet From The NORT	H Line and 2310	Feet From The EAST Line	
Section 28	22S	Range Nheiher DF, RKB, RT, GR, etc.)	NMPM LEA County	
11. Check	Appropriate Box to Indic	cate Nature of Notice, R	eport, or Other Data	
NOTICE OF INT	ENTION TO:	SUB	SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	GOPNS. PLUG AND ABANDONMENT	
PULL OR ALTER CASING		CASING TEST AND CE	MENT JOB	
OTHER:		OTHER:		
12. Describe Proposed or Completed Open work) SEE RULE 1103.	itions (Clearly state all pertinent de	etails, and give persinent dates, inc	luding estimated date of starting any proposed	
TALKED TO E.L. GONZALES. 3/18/02 RAN IN WITH 7" CIBP; PULL UP HOLE; WOC 3/19/02 RUN IN HOLE; TAG CI 3/19/02 PULL UP TO 1328'; PL 3/19/02 RIG UP WIRE LINE; R RUN IN HOLE TO 1328', PUMP 3/20/02 RAN IN WITH TUBING 3/20/02 RAN IN HOLE WITH P 3/20/02 PERF AT 170', NIPPLE 3/21/02 TEST TO 500# GOOD, 3/22/02 TAG AT 92'; PUMP 20	SET AT 3350'; CIRCULATE HO EMENT AT 3241'; PULL UP TO IMP 25 SACKS CEMENT; DISP AN IN HOLE; TAG CEMENT AT 50 SACKS, DISPLACE TO 100 ; TAG CEMENT AT 960'; LOAD ACKER, SET AT 505'; FOUND B ; DOWN BOP, NIPPLE UP WEL TAG AND PERF AT 92'; PUMP	DLE W/122 BBL. MLF; PUMP 2 2561'; PUMP 25 SACKS CEME LACE TO 1169'; PULL OUT DF 2394'; PULL OUT OF HOLE W 6'; PULL OUT WITH TUBING; 7" CASING; PUMP INTO 1 EP BAD CASING FROM 205' TO 8 LHEAD; PUMP 100 SACKS CE 50 SACKS OF CEMENT; DISF EE 2 SACKS INTO PERFS. SIP	F HOLE RAN 7" PACKER, LOOK FOR HOLE  //TH WIRE LINE AND TUBING AND PACKER;  SHUT WELL IN  M AT 100#; PULL OUT WITH TUBING  00'; PULL OUT WITH PACKER  EMENT; DISPLACE WITH 112 BLS	
I hereby certify that the information above is true	and complete to the best of my knowledge	e and belief	F. (6)	
SIONATURE AUGUS	eller	THE SR. STAFF / TO	DA ENGIL PATE 4/3/2002	
TYPE OR PRINT NAME P. N	MUELLEZ		TELEPHONE NO (915) 683-0555	
(Thus space for State Use)  APPROVED BY  CONDITIONS OF APPROVAL IF AUT:	1. X/d	me Compliance	Africa DATE 06/02	
@ M IN			C	