

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

N. M. OIL CONS. CO.
P. O. BOX 1980
HOBBS, NEW MEXICO 88240

Form Approved.
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

5. LEASE	LC-061936
6. IF INDIAN, ALLOTTEE OR TRIBE NAME	-
7. UNIT AGREEMENT NAME	-
8. FARM OR LEASE NAME	Cotton Draw Unit
9. WELL NO.	69
10. FIELD OR WILDCAT NAME	Paduca Delaware North
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA	Sec. 34, T-24-S, R-32-E
12. COUNTY OR PARISH	Lea
13. STATE	New Mexico
14. API NO.	
15. ELEVATIONS (SHOW DF, KDB, AND WD)	3517' (DF)

1. oil well gas well other


2. NAME OF OPERATOR
Texaco Inc.

3. ADDRESS OF OPERATOR
P.O. Box 728, Hobbs, N. M. 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1980' FSL & 1980' FWL
AT TOP PROD. INTERVAL: (Unit Letter 'K')
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF <input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	<input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE <input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES <input type="checkbox"/>	<input type="checkbox"/>
ABANDON* <input type="checkbox"/>	<input type="checkbox"/>
(other) _____	



(NOTE: Report results of multiple completion or zone change on Form 9-330.)

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- Rigged up. Pull rods & pump. Install BOP. Pull tubing.
- Clean out.
- Set pkr. @ 4729'. Acidize perfs. 4795' - 4852' w/1000 gals. 7 1/2% NEFE Acid 25 Ball Sealers. Flush w/20 Bbls. KCL Water.
- Install pumping equipment. On 24 Hr. Potential Test ending 5/20/82, Well pumped 12 BO & 44 BW, GOR 20804.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct
SIGNED [Signature] TITLE Asst. Dist. Mgr DATE 5-27-82

(This space for Federal or State office use)
APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD
PETER W. CHESTER
JUL 14 1982
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

See instructions on Reverse Side

RECEIVED
JUL 15 1982
G.C.D.
HOBBS OFFICE