

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

CONTACT RECORDING  
OFFICE FOR THE  
OF COPIES REQUIRED  
(Other instructions on re-  
verse side)

BLM Roswell District  
Modified Form No.  
NMDG-3160-4

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <u>Injection</u>		5. LEASE DESIGNATION AND SERIAL NO. <u>NM-7951</u>
2. NAME OF OPERATOR <u>United Gas Search, Inc.</u>		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR <u>P. O. Box 755, Hobbs, New Mexico 88241-0755</u>		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface  <u>660' FNL &amp; 660' FWL</u>		8. FARM OR LEASE NAME <u>Leonard Brothers</u>
14. PERMIT NO. <u>30-025-25981</u>		9. WELL NO. <u>26</u>
15. ELEVATIONS (Show whether DF, RT, OR, etc.) <u>3010 KB</u>		10. FIELD AND POOL, OR WILDCAT <u>South Leonard Queen</u>
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>Sec 13 T26S R37E</u>
17. DESCRIBE PROMISED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*		12. COUNTY OR PARISH <u>Lea</u>
		13. STATE <u>NM</u>

**Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data**

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input checked="" type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	
(Other) <u>Set Bridge Plug</u> <input checked="" type="checkbox"/>			

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

It is proposed to set retrievable bridge plug at 3500 to shut off Penrose perms 3516-3524 and acidize Queen perms 3442-3486 with 5,000 gal 15% acid. Return to injection.

RECEIVED  
 SEP 17 8 29 AM '90  
 O&G  
 AREA

18. I hereby certify that the foregoing is true and correct

SIGNED *Alvin Scimech* TITLE Agent DATE 9/13/90

(This space for Federal or State office use)  
 Approved by Alvin Scimech TITLE PETROLEUM ENGINEER DATE 9-18-90  
 CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

RECEIVED

SEP 21 1990

612  
ISSUE OFFICE