

N. M. OIL CONS. COMMISSION  
P. O. BOX 1980  
HOBBS, NEW MEXICO 88240

0+5-MMS-Roswell, 1-File, 1-Engr. Jim, 1-Foreman CK, 1-JA, 1-BW, 1-Laura Richardson-Midland

Form 9-331  
Dec. 1973

Form Approved.  
Budget Bureau No. 42-R1424

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other ☐

2. NAME OF OPERATOR  
Getty Oil Company

3. ADDRESS OF OPERATOR  
P.O. Box 730, Hobbs, New Mexico 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: Unit Ltr I, 990' FEL, 1980' FSL  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐  
(other) Repair tubing

☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐  
(X)

5. LEASE  
LC-032650 (b)  
6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
7. UNIT AGREEMENT NAME  
8. FARM OR LEASE NAME  
A.B. Coates "C"  
9. WELL NO.  
18  
10. FIELD OR WILDCAT NAME  
Justis Ellen - Tub- Drk. - Blby.  
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec. 24, T-25S, R-37E  
12. COUNTY OR PARISH  
Lea  
13. STATE  
NM  
14. API NO.  
15. ELEVATIONS (SHOW DF, KDB, AND WD)  
3077 DF

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

9/7/82 Rig up Clarke. Pull both strings rods & pumps. Ran Dialog found 16 bad joints tbg. Pull both strings tbg 6' sub parted on long string. 1" tbg & pkr in hole.  
9/8/82 Ran overshot did not catch fish @ 6115'. Pull overshot ran 6 1/4" x 5' shoe to 4750'.  
9/9/82 Ran mill. Mill 6115-6118 1/2'. Pull mill. Ran 5 7/8" over shot. Tag 6117'. Push to 6138'. Pull no recovery.  
9/10/82 Ran 5 7/8" overshot 6130 = fish no recovery. Ran new overshot no catch. Ran impression block 2 3/8" tbg looking up.  
9/11/82 Ran overshot to 6138'. Pull & recover pkr & all fish.  
9/13/82 Test long string. Locset pkr @ 6143'. SN @6078'. On-Off at 6109'. Anchor 5985'  
9/14/82 Ran short string to 5980'. Anchor @ 5985'. SN @ 5978'. Ran pump on long string.  
9/15/82 Ran short string pump. Rig down. Placed well back on production.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED D. H. Crockett TITLE Area Superintendent September 17, 1982

ACCEPTED FOR RECORD (This space for Federal or State office use)  
APPROVED BY PETER W. CHESTER TITLE DATE  
CONDITIONS OF APPROVAL IF ANY  
SEP 29 1982

RECEIVED  
SEP 21 1982

OIL & GAS  
MINERALS MGMT. SERVICE  
ROSWELL, NEW MEXICO