

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-30828
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-9613
7. Lease Name or Unit Agreement Name WEST DOLLARHIDE DRINKARD UNIT
8. Well No. 106
9. Pool name or Wildcat DOLLARHIDE TUBB DRINKARD
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR-3182', KB-3200'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL GAS WELL OTHER

2. Name of Operator
TEXACO PRODUCING INC.

3. Address of Operator
P. O. Box 3109 Midland, Texas 79702

4. Well Location
Unit Letter J : 1363 Feet From The SOUTH Line and 2542 Feet From The EAST Line
Section 32 Township 24-SOUTH Range 38-EAST NMPM LEA County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: COMPLETION <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- MIRU DA&S. CLEAN OUT CASING TO PBTD OF 6872'. TESTED CASING TO 3000# FOR 30 MINUTES 03-08-91.
- UNION RAN GR-CCL FROM 6872' TO 5900'. PERFED w/ 1 JSPF: 6620-24, 6636-41, 6646-52, 6654-58, 6660-64, 6701-07, 6720-42, 6824-28. 55 HOLES.
- HALLIBURTON ACIDIZED WITH 7800 GAL 15% NEFE. SWAB 15 BNO, 160 BLW & 5 BW IN 12 HOURS 03-11-91.
- TIH & SET RBP @ 6595'. TESTED TO 3000#.
- UNION PERFED w/ 1 JSPF: 6399-6402, 6404-08, 6411-26, 6428-39, 6441-47, 6453-63, 6467-76, 6479-83, 6494-97, 6525-29, 6565-69. 73 HOLES. 03-12-91.
- HALLIBURTON ACIDIZED WITH 10200 GAL 15% NEFE. 03-13-91. WELL FLOWED 57 BNO, 242 BLW & 10 BW IN 23 HOURS 03-14-91.
- TOH WITH RBP. TIH WITH 2 7/8 TUBING, PUMP & RODS. SEATING NIPPLE @ 6834'.
- PUMPED WELL 24 HOURS 03-28-91. RECOVERED 149 BNO, 403 BW & 70 MCF.
- TESTING.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE C. P. Basham/cwd TITLE DRILLING SUPERINTENDENT DATE 03-29-91

TYPE OR PRINT NAME C. P. BASHAM TELEPHONE NO. 915-6884620

(This space for State Use) ORIGINAL SIGNATURE BY BERRY SEXTON
DISTRICT SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

APR 03 1991

RECEIVED

APR 02 1991

1991

LIBRARY