

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

PERMIT IN TRI STATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-037667
7488

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL GAS WELL OTHER DEPLETED

2. NAME OF OPERATOR
PAN AMERICAN PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR
BOX 68, HOBBS, N. M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
330' FSL x 1650' FEL, Sec 9 (Unit O, SW/4 SE/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3284' R. D. B.

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
MYERS "B" Federal

9. WELL NO.
24

10. FIELD AND POOL, OR WELDCAT
FOULER BLINDBRY

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
9-24-37 N M P M

12. COUNTY OR PARISH
LEA

13. STATE
N. M.

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) _____	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

On 9-2-69, physical abandonment of well was made and abandonment marker set. Well P+ A as follows:

Spotted 40 sz cement plug @ 5639. (Prfs: 5513-99)

Shot 4 1/2" @ 3405 & pulled from 3280. 25 sz cement plug in and out of stub.

Shot & pulled 7 7/8" from 1385; 25 sz. cement plug in and out of stub; 25 sz @ 1020;

Spotted 40 sz @ 340. 10 sz @ surface w/ P+A marker.

INTERVALS filled w/ mud.

Final cleanup shall be made and ground restored to contour.

18. I hereby certify that the foregoing is true and correct

SIGNED _____ TITLE AREA SUPERINTENDENT DATE SEP 4 1969

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

0+ 4- USGS - H
1- NSW
2- WFS
1- SUSP
1- RRY

APPROVED
SEP 2 1970

*See Instructions on Reverse Side
J L GORDON
ACTING DISTRICT ENGINEER

RECEIVED

SEP 20 1970

**OIL CONSERVATION COMM.
HOBBS, N. M.**