District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Page 1 of 4

Incident ID	
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party	ETC Texas Pipeline LTD	OGRID 371183				
Contact Name	Lyanne Lara	Contact Telephone 432-425-5710				
Contact email	Lyanne.Lara@energytransfer.com	Incident # (assigned by OCD) nAPP2206954187				
Contact mailing address 600 N. Marienfeld St. Suite 700 Midland, TX 79701						

Location of Release Source

Latitude 32.2411479_

(NAD 83 in decimal degrees to 5 decimal places)

Site Name ETC Shurvesa Interconnect	Site Type Crude Interconnect
Date Release Discovered 03/10/2022	API# (if applicable)

Unit Letter	Section	Township	Range	County
Р	S1	T24S	R32E	Lea

Surface Owner: State Federal Tribal Private (Name: Bureau of Land Management_____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

Crude Oil	Volume Released (bbls) 22.7	Volume Recovered (bbls) 3
Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	Yes No
Condensate	Volume Released (bbls)	Volume Recovered (bbls)
Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
Other (describe)	Volume/Weight Released (provide units) 270 gallons	Volume/Weight Recovered (provide units)

Cause of Release

The chemical hose had come apart from the fitting above the valve on the pipeline side of the pig launcher. A check valve also leaked due to not being sealed 100%. The valve was closed with leak source isolated. A vacuum truck was onsite to recover what could be picked up. Remediation is underway. Corrosion Inhibitor 330 gallon tank had just been filled prior to the spill; at the time of the spill, there was only 60 gallons remaining in tank – estimated 270 gallons released.

Page 2 of

Was this a major release as defined by	If YES, for what reason(s) does the responsible party consider this a major release?
19.15.29.7(A) NMAC?	
🗌 Yes 🖾 No	
If YES, was immediate no	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

 \square The source of the release has been stopped.

The impacted area has been secured to protect human health and the environment.

Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.

All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

-

					Liquid Sp	oill in Soil Work	book					
Facility Name:	Shurvesa lı	nterconnect										
Spill Date:	3/10/2022											
Liquid Recovered												
(vacuum truck)	0	(bbls)										
Barrow Market		A	A	A		A	A	A	A	A 12 111	A	A
Description	Area "A"	Area "B"	Area "C"	Area "D"	Area "E"	Area "F"	Area "G"	Area "H"	Area "I"	Area "J"	Area "K"	Area "L"
Length (ft.)	10	6	67								· · · · · · · · · · · · · · · · · · ·	-
Width (ft.)		14	3			-						
Depth (in.)	24.00	12.00	8.00									
Depth (feet)		1.00	0.67		0.00	0.00	0.00	0,00	0.00	0.00	8.00	0.00
ft3 Total Soil	420.00		134								· · · · · · · · · · · · · · · · · · ·	
% Saturated Soil	100%	100%	100%									
of 100% Saturated												
Soil	420.00	<u>84</u>	134	<u>0</u>			4		Q			
Porosity Factor	Sand	Sand	Sand									
Area Spill Volume												
(bbls in soil)												
Total Spill from all	50.0000											
areas (in Soil)	0.0	(bbls)										
				3								
Total Spill Volume ไ	N REALING		1	and the second		Construction of the second						
from all areas.		(bbls)	Net Spill volume	22.7	(bbls)	954.44	(Gallons)					

Corrosion Inhibitor – 330 gallon tank had just been filled prior to the spill; at the time of the spill, there was only 60 gallons remaining in tank – estimated 270 gallons released

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator: (OGRID:			
ETC Texas Pipeline, Ltd.	371183			
8111 Westchester Drive	Action Number:			
Dallas, TX 75225	92886			
	Action Type:			
	[C-141] Release Corrective Action (C-141)			
CONDITIONS				

Created By Condition Condition Date 4/12/2022 jharimon None

Page 4 of 4

Action 92886