

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural  
Resources Department

Form C-141  
Revised August 24, 2018  
Submit to appropriate OCD District office

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

|                |                |
|----------------|----------------|
| Incident ID    | nAPP2229734031 |
| District RP    |                |
| Facility ID    | fAPP2129922900 |
| Application ID |                |

## Release Notification

### Responsible Party

|  |   |
|--|---|
| Responsible Party: BTA Oil Producers, LLC                    | OGRID: 260297                               |
| Contact Name: Bob Hall                                       | Contact Telephone: 432-682-3753             |
| Contact email: bhall@btaoil.com                              | Incident # (assigned by OCD) nAPP2229734031 |
| Contact mailing address: 104 S. Pecos St., Midland, TX 79701 |   |

### Location of Release Source

Latitude: 32.05169 Longitude: -103.60570

(NAD 83 in decimal degrees to 5 decimal places)

|                                     |                                    |
|-------------------------------------|------------------------------------|
| Site Name: Mesa B #2 Tank Battery   | Site Type: Tank Battery            |
| Date Release Discovered: 10/21/2022 | API# (if applicable) Nearest well: |

| Unit Letter | Section | Township | Range | County |
|-------------|---------|----------|-------|--------|
| P           | 7       | 26S      | 33E   | Lea    |

Surface Owner:  State  Federal  Tribal  Private (Name: AE&J Royalties LLC)

### Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

|  |  |   |
|--|--|---|
| <input type="checkbox"/> Crude Oil                 | Volume Released (bbls)   | Volume Recovered (bbls)   |
| <input checked="" type="checkbox"/> Produced Water | Volume Released (bbls) 21 BBL  | Volume Recovered (bbls) 12 BBL                                      |
|  | Is the concentration of dissolved chloride in the produced water >10,000 mg/l? | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No |
| <input type="checkbox"/> Condensate                | Volume Released (bbls)   | Volume Recovered (bbls)   |
| <input type="checkbox"/> Natural Gas               | Volume Released (Mcf)  | Volume Recovered (Mcf)  |
| <input type="checkbox"/> Other (describe)          | Volume/Weight Released (provide units)   | Volume/Weight Recovered (provide units)                             |

Cause of Release

Steel/Poly Line Transition Fitting failure. The fitting failed, releasing produced water on the northeast corner of the tank battery pad immediately outside of the secondary containment. Recovered 12 BW with vacuum truck.

Spill volume calculation attached.

|                |                |
|----------------|----------------|
| Incident ID    | nAPP2229734031 |
| District RP    |                |
| Facility ID    | fAPP2129922900 |
| Application ID |                |

|   |  |
|---|--|
| Was this a major release as defined by 19.15.29.7(A) NMAC?<br><br><input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, for what reason(s) does the responsible party consider this a major release? |
| If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?                          |  |

### Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

|  |
|--|
| <input checked="" type="checkbox"/> The source of the release has been stopped.<br><input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment.<br><input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.<br><input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.   |
| If all the actions described above have <u>not</u> been undertaken, explain why:   |
| Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.  |
| I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. |
| Printed Name: <b>Bob Hall</b> Title: <b>Environmental Manager</b><br><br>Signature: <u></u> Date: <b>10/24/2022</b><br><br>email: <b>bhall@btaoil.com</b> Telephone: <b>432-682-3753</b>  |
| <b><u>OCD Only</u></b><br><br>Received by: <u>Jocelyn Harimon</u> Date: <u>10/24/2022</u>  |

**Location** Mesa B #2 Poly Line Coupling

**API #**

**Spill Date** 10/21/2022

**Spill Dimensions**

**ENTER** - Length of Spill  feet

**ENTER** - Width of Spill  feet

**ENTER** - Saturation Depth of Spill  inches

**ENTER** - Porosity Factor  decimal

**Oil Cut - Well Test / Vessel Throughput or Contents**

Oil

Water

Calculated Oil Cut

**Volume Recovered in Truck / Containment**

**ENTER** - Recovered Oil  BBL

**ENTER** - Recovered Water  BBL

**Calculated Values**

Release of Oil in Soil - Unrecovered  BBL

Release of Water in Soil - Unrecovered  BBL

Unrecovered Total Release  BBL

**Calculated Values**

Total Release of Oil  BBL

Total Release of Water  BBL

Total Release  BBL

| Types of Soil      | Porosity Factor |
|--------------------|-----------------|
| Gravel             | 0.25            |
| Sand               | 0.20            |
| Clay/silt/sand Mix | 0.15            |
| Clay               | 0.05            |
| Caliche            | 0.03            |
| Unknown            | 0.25            |

**(Length X Width X Depth X 1 ft/12 in) X Porosity**


5.615 ft<sup>3</sup> / BBL

X

**Oil Cut  
(or Water Cut)**

### Mesa B #2 Tank Battery – 10/21/2022

Steel/Poly Line Transition Fitting failure.  
32.051691 -103.605700



**District I**  
 1625 N. French Dr., Hobbs, NM 88240  
 Phone:(575) 393-6161 Fax:(575) 393-0720

**District II**  
 811 S. First St., Artesia, NM 88210  
 Phone:(575) 748-1283 Fax:(575) 748-9720

**District III**  
 1000 Rio Brazos Rd., Aztec, NM 87410  
 Phone:(505) 334-6178 Fax:(505) 334-6170

**District IV**  
 1220 S. St Francis Dr., Santa Fe, NM 87505  
 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 152932

**CONDITIONS**

|   |   |
|---|---|
| Operator:<br>BTA OIL PRODUCERS, LLC<br>104 S Pecos<br>Midland, TX 79701 | OGRID:<br>260297  |
|   | Action Number:<br>152932                                  |
|   | Action Type:<br>[C-141] Release Corrective Action (C-141) |

**CONDITIONS**

| Created By | Condition | Condition Date |
|------------|-----------|----------------|
| jharimon   | None      | 10/24/2022     |