

Field:

Station Name:

# Certificate of Analysis

Number: 6030-24010172-001A

**Artesia Laboratory** 200 E Main St. Artesia, NM 88210 Phone 575-746-3481

Jan. 17, 2024

**Chandler Montgomery** Occidental Petroleum 1502 W Commerce Dr. Carlsbad, NM 88220

> Sampled By: Mike Armijo

Falcon Ridge CPF Flare Fuel Sample Of: Gas Composite N/A Sample Date: 01/15/2024 11:45

Station Number: Station Location: Fuel Gas Sample Conditions: 123 psig Ambient: 78 °F 01/15/2024 11:45 Sample Point: Inlet Effective Date:

NEW\_MEXICO Formation: Flow Rate: N/A

PERMIAN RESOURCES

County: Lea Method: GPA-2261M Well Name: N/A Cylinder No: 1111-008297

Type of Sample: : Spot-Cylinder Instrument: 70104251 (Inficon GC-MicroFusion)

Heat Trace Used: N/A Last Inst. Cal.: 01/15/2024 0:00 AM

Sampling Method: : Fill and Purge Analyzed: 01/16/2024 13:57:29 by EBH

Sampling Company: : SPL

# **Analytical Data**

Components	Un-normalized Mol %	Mol. %	Wt. %	GPM at 14.65 psia	
Hydrogen Sulfide	0.0000	0.0005	0.0008		
Nitrogen	1.3597	1.3866	1.7817		
Carbon Dioxide	1.0467	1.0674	2.1548		
Methane	73.3808	74.8346	55.0684		
Ethane	12.2177	12.4597	17.1853	3.326	
Propane	6.6220	6.7532	13.6595	1.857	
Iso-Butane	0.7649	0.7801	2.0798	0.255	
n-Butane	1.6468	1.6794	4.4774	0.528	
Iso-Pentane	0.4382	0.4469	1.4790	0.163	
n-Pentane	0.4004	0.4083	1.3513	0.148	
Hexanes	0.1293	0.1319	0.5214	0.054	
Heptanes	0.0450	0.0459	0.2110	0.021	
Octanes	0.0043	0.0044	0.0231	0.002	
Nonanes Plus	0.0011	0.0011	0.0065	0.001	
	98.0569	100.0000	100.0000	6.355	
Calculated Physical	Properties	Tot	al	C9+	
Calculated Molecular	Weight	21.8	30	128.26	
Compressibility Factor		0.996	62		
Relative Density Real	Relative Density Real Gas		53	4.4283	
GPA 2172 Calculatio	n:				
Calculated Gross BT	U per ft <sup>3</sup> @ 14.65 ps	sia & 60°F			
Real Gas Dry BTU		1270	.6	6974.4	
Water Sat. Gas Base	BTU	1248	.9	6852.4	
Ideal, Gross HV - Dry	at 14.65 psia	1265		6974.4	
Ideal, Gross HV - Wet		1243	.7	6852.4	
Comments: H2S Fie					

FMP/LSE N/A,

Hydrocarbon Laboratory Manager

Quality Assurance: The above analyses are performed in accordance with ASTM, UOP, GPA guidelines for quality

assurance, unless otherwise stated.

#### **UPSET FLARING EVENT SPECIFIC JUSTIFICATIONS FORM**

Facility: Falcon Ridge CPF Flare Date: 05/25/2024

**Duration of Event:** 30 Minutes **MCF Flared:** 50

Start Time: 11:10 PM End Time: 11:40 PM

Cause: Emergency Flare > Third Party Downstream Activity > Targa > Equipment Issues

Method of Flared Gas Measurement: Gas Flare Meter

# 1. Reason why this event was beyond Operator's control:

The emissions event was caused by the unforeseen, unexpected, sudden, and unavoidable interruption, restriction, or complete shut-in of a gas pipeline by a third-party pipeline compressor station operator, which impacted Oxy's ability to send gas to them. This interruption, restriction, or complete shut-in of the gas pipeline by a third-party pipeline compression station operator is downstream of Oxy's custody transfer point and out of Oxy's control to foresee, avoid or prevent from happening and did not stem from any of Oxy's upstream facility activity that could have been foreseen and avoided, and could not have been avoided by good design, operation, and preventative maintenance practices. In this case, Targa suddenly and unexpectedly had equipment issues on their end, when which in turn caused an over-pressuring of their sales gas line, which then caused high line pressure to occur, which then triggered a flaring event to occur. This event could not have been foreseen, avoided, or prevented from happening as this event occurred with no advance notice or warning.

# 2. Steps Taken to limit duration and magnitude of venting or flaring:

It is OXY's policy to route its stranded gas to a flare during an unforeseen and unavoidable emergency or malfunction, that is beyond Oxy's control to avoid, prevent or foresee, to minimize emissions as much as possible as part of the overall steps taken to limit duration and magnitude of flaring. In this case, Targa suddenly and unexpectedly had equipment issues on their end, when which in turn caused an over-pressuring of their sales gas line, which then caused high line pressure to occur, which then triggered a flaring event to occur. This event could not have been foreseen, avoided, or prevented from happening as this flaring event occurred with no advance notice or warning. Oxy's operations were running in normal operations until Targa had issues on their end. As soon as flaring was triggered, the well optimizer adjusted injection rates and Oxy field personnel choked back all wells to help minimize and mitigate emissions. This event is out of OXY's control, yet OXY made every effort to control and minimize emissions as much as possible.

## 3. Corrective Actions taken to eliminate the cause and reoccurrence of venting or flaring:

Oxy is unable to take any corrective actions to eliminate the cause and potential reoccurrence of a downstream third-party owned and operated sales line issue, as this is downstream of Oxy's custody transfer point and out of Oxy's control to foresee, avoid, prevent from happening or reoccur. When Targa has equipment issues, unplanned maintenance issues or greatly struggles to handle the volume of gas being sent to them by Oxy, Targa then restricts Oxy's ability to send its gas, which then prompts Oxy to route all its stranded gas not pushed into the Targa sales gas pipeline, to flare. OXY makes every effort to control and minimize emissions as much as possible. The only actions that Oxy can take and handle that is within its control, is to continually communicate with Targa personnel, who own and operate the sales gas pipeline, when possible, during these types of circumstances.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

DEFINITIONS

Action 357338

#### **DEFINITIONS**

Operator:	OGRID:
OXY USA INC	16696
P.O. Box 4294	Action Number:
Houston, TX 772104294	357338
	Action Type:
	[C-129] Amend Venting and/or Flaring (C-129A)

#### **DEFINITIONS**

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application:

- this application's operator, hereinafter "this operator";
- · venting and/or flaring, hereinafter "vent or flare";
- any notification or report(s) of the C-129 form family, hereinafter "any C-129 forms";
- the statements in (and/or attached to) this, hereinafter "the statements in this";
- and the past tense will be used in lieu of mixed past/present tense questions and statements.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III 1000 Rio Brazos Rd., Aztec, NM 87410

Phone:(505) 334-6178 Fax:(505) 334-6170 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

QUESTIONS

Action 357338

#### **QUESTIONS**

Q020110110	
Operator:	OGRID:
OXY USA INC	16696
P.O. Box 4294	Action Number:
Houston, TX 772104294	357338
	Action Type:
	[C-129] Amend Venting and/or Flaring (C-129A)
QUESTIONS	
Prerequisites	

Prerequisites		
Any messages presented in this section, will prevent submission of this application. Please resolve these issues before continuing with the rest of the questions.		
Incident ID (n#)	Unavailable.	
Incident Name	Unavailable.	
Incident Type	Flare	
Incident Status	Unavailable.	
Incident Facility	[fAPP2331575145] Falcon Ridge Tankless CPF	
Only valid Vent, Flare or Vent with Flaring incidents (selected above in the Application Details section) that are assigned to your current operator can be amended with this C-129A application.		

Determination of Reporting Requirements		
Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide addional guidance.		
Was this vent or flare caused by an emergency or malfunction	Yes	
Did this vent or flare last eight hours or more cumulatively within any 24-hour period from a single event	No	
Is this considered a submission for a vent or flare event	Yes, minor venting and/or flaring of natural gas.	
An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during v  Was there at least 50 MCF of natural gas vented and/or flared during this event	enting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.  Yes	
Did this vent or flare result in the release of <b>ANY</b> liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No	
Was the vent or flare within an incorporated municipal boundary or withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No	

Equipment Involved		
Primary Equipment Involved	Other (Specify)	
Additional details for Equipment Involved. Please specify	Emergency Flare > Third Party Downstream Activity > Targa > Equipment Issues	

Representative Compositional Analysis of Vented or Flared Natural Gas		
Please provide the mole percent for the percentage questions in this group.		
Methane (CH4) percentage	75	
Nitrogen (N2) percentage, if greater than one percent	1	
Hydrogen Sulfide (H2S) PPM, rounded up	5	
Carbon Dioxide (C02) percentage, if greater than one percent	1	
Oxygen (02) percentage, if greater than one percent	0	
If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.		
Methane (CH4) percentage quality requirement	0	
Nitrogen (N2) percentage quality requirement	0	
Hydrogen Sufide (H2S) PPM quality requirement	0	
Carbon Dioxide (C02) percentage quality requirement	0	
Oxygen (02) percentage quality requirement	0	

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

QUESTIONS, Page 2

Action 357338

QUESTIONS	(continued)

Operator:	OGRID:
OXY USA INC	16696
P.O. Box 4294	Action Number:
Houston, TX 772104294	357338
	Action Type:
	[C-129] Amend Venting and/or Flaring (C-129A)

#### QUESTIONS

Date(s) and Time(s)	
Date vent or flare was discovered or commenced	05/25/2024
Time vent or flare was discovered or commenced	11:10 PM
Time vent or flare was terminated	11:40 PM
Cumulative hours during this event	1

Measured or Estimated Volume of Vented or Flared Natural Gas		
Natural Gas Vented (Mcf) Details	Not answered.	
Natural Gas Flared (Mcf) Details	Cause: Other   Other (Specify)   Natural Gas Flared   Released: 50 MCF   Recovered: 0 MCF   Lost: 50 MCF.	
Other Released Details	Not answered.	
Additional details for Measured or Estimated Volume(s). Please specify	Gas Flare Meter	
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.	

Venting or Flaring Resulting from Downstream Activity		
Was this vent or flare a result of downstream activity	Yes	
Was notification of downstream activity received by this operator	No	
Downstream OGRID that should have notified this operator	[24650] TARGA MIDSTREAM SERVICES LLC	
Date notified of downstream activity requiring this vent or flare		
Time notified of downstream activity requiring this vent or flare	Not answered.	

Steps and Actions to Prevent Waste	
For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control	True
Please explain reason for why this event was beyond this operator's control	The emissions event was caused by the unforeseen, unexpected, sudden, and unavoidable interruption, restriction, or complete shut-in of a gas pipeline by a third-party pipeline compressor station operator, which impacted Oxy's ability to send gas to them. This interruption, restriction, or complete shut-in of the gas pipeline by a third-party pipeline compression station operator is downstream of Oxy's custody transfer point and out of Oxy's control to foresee, avoid or prevent from happening and did not stem from any of Oxy's upstream facility activity that could have been foreseen and avoided, and could not have been avoided by good design, operation, and preventative maintenance practices. In this case, Targa suddenly and unexpectedly had equipment issues on their end, when which in turn caused an over-pressuring of their sales gas line, which then caused high line pressure to occur, which then triggered a flaring event to occur. This event could not have been foreseen, avoided, or prevented from happening as this event occurred with no advance notice or warning.
Steps taken to limit the duration and magnitude of vent or flare	It is OXY's policy to route its stranded gas to a flare during an unforeseen and unavoidable emergency or malfunction, that is beyond Oxy's control to avoid, prevent or foresee, to minimize emissions as much as possible as part of the overall steps taken to limit duration and magnitude of flaring. In this case, Targa suddenly and unexpectedly had equipment issues on their end, when which in turn caused an over-pressuring of their sales gas line, which then caused high line pressure to occur, which then triggered a flaring event to occur. This event could not have been foreseen, avoided, or prevented from happening as this

	flaring event occurred with no advance notice or warning. Oxy's operations were running in normal operations until Targa had issues on their end. As soon as flaring was triggered, the well optimizer adjusted injection rates and Oxy field personnel choked back all wells to help minimize and mitigate emissions. This event is out of OXY's control, yet OXY made every effort to control and minimize emissions as much as possible.
Corrective actions taken to eliminate the cause and reoccurrence of vent or flare	Oxy is unable to take any corrective actions to eliminate the cause and potential reoccurrence of a downstream third-party owned and operated sales line issue, as this is downstream of Oxy's custody transfer point and out of Oxy's control to foresee, avoid, prevent from happening or reoccur. When Targa has equipment issues, unplanned maintenance issues or greatly struggles to handle the volume of gas being sent to them by Oxy, Targa then restricts Oxy's ability to send its gas, which then prompts Oxy to route all its stranded gas not pushed into the Targa sales gas pipeline, to flare. OXY makes every effort to control and minimize emissions as much as possible. The only actions that Oxy can take and handle that is within its control, is to continually communicate with Targa personnel, who own and operate the sales gas pipeline, when possible, during these types of circumstances.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

# **State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505**

ACKNOWLEDGMENTS

Action 357338

#### **ACKNOWLEDGMENTS**

Operator:	OGRID:	
OXY USA INC	16696	
P.O. Box 4294	Action Number:	
Houston, TX 772104294	357338	
	Action Type:	
	[C-129] Amend Venting and/or Flaring (C-129A)	

#### **ACKNOWLEDGMENTS**

$\overline{\lor}$	I acknowledge that with this application I will be amending an existing incident file (assigned to this operator) for a vent or flare event, pursuant to 19.15.27 and 19.15.28 NMAC.
V	I acknowledge that amending an incident file does not replace original submitted application(s) or information and understand that any C-129 forms submitted to the OCD will be logged and stored as public record.
V	I hereby certify the statements in this amending report are true and correct to the best of my knowledge and acknowledge that any false statement may be subject to civil and criminal penalties under the Oil and Gas Act.
V.	I acknowledge that the acceptance of any C-129 forms by the OCD does not relieve this operator of liability should their operations have failed to adequately investigate, report, and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment.
V	I acknowledge that OCD acceptance of any C-129 forms does not relieve this operator of responsibility for compliance with any other applicable federal, state, or local laws and/or regulations.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 357338

### **CONDITIONS**

Note that the second se	
Operator:	OGRID:
OXY USA INC	16696
P.O. Box 4294	Action Number:
Houston, TX 772104294	357338
	Action Type:
	[C-129] Amend Venting and/or Flaring (C-129A)

#### CONDITIONS

Created By		Condition Date
shelbyschoepf	If the information provided in this report requires further amendment(s), submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	6/25/2024