Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 444118

QUESTIONS			
Operator: Franklin Mountain Energy 3, LLC	OGRID: 331595		
	Action Number: 444118		
	Action Type: [NOTIFY] Notification Of Liner Inspection (C-141L)		

QUESTIONS

Prerequisites	
Incident ID (n#)	nAPP2505041911
Incident Name	NAPP2505041911 SOUTH VACUUM UNIT 351 SWD @ 0
Incident Type	Produced Water Release
Incident Status	Initial C-141 Approved

Location of Release Source	
Site Name	South Vacuum Unit 351 SWD
Date Release Discovered	02/18/2025
Surface Owner	State

Liner Inspection Event Information

Please answer all the questions in this group.	
What is the liner inspection surface area in square feet	5,500
Have all the impacted materials been removed from the liner	Yes
Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC	03/24/2025
Time liner inspection will commence	09:00 AM
Please provide any information necessary for observers to liner inspection	Inspecting lined tank containment
Please provide any information necessary for navigation to liner inspection site	Coordinates: 32.705858, -103.426609

Page 1	of 2
OUFSTIONS	

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

CONDITIONS

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

Operator:	OGRID:	
Franklin Mountain Energy 3, LLC	331595	
44 Cook Street	Action Number:	
Denver, CO 80206	444118	
	Action Type:	
	[NOTIFY] Notification Of Liner Inspection (C-141L)	

Created By		Condition Date
lluig	Failure to notify the OCD of liner inspections including any changes in date/time per the requirements of 19.15.29.11.A(5)(a)(ii) NMAC, may result in the inspection not being accepted.	3/20/2025

CONDITIONS

Action 444118