## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

		-
DISTRIBUTION		/
SANTA FE	$L_{Z}$	
FILE	7	
U.S.G.S.	]	
LAND OFFICE		
OPERATOR		

## OIL CONSERVATION DIVISION

[ 0	ISTRIBUTION		P. O. BOX 2088			Porm C-103			
SANT	AFE		SANTA FE, NEW MEXICO 87501			Revised 10	,-1-,0		
FILE				·		Sa. Indicate Type of Lease			
U.S.G	.s.				•				
LAND	OFFICE					State Fee			
PETATOR					S. State Oil & Gas Lease No.				
(00	HOT USE THIS FOR	SUNDRY NO	TICES AND REPO	RTS ON	WELLS BACK TO A DIFFERENT RESERVOIR.				
01L WELL	GAS WELL		'HER•			7. Unit Agreement home	222		
2. Name of Operator						8. Farm or Lease Name	8. Farm or Lease Name		
BLACK OIL, INC.					Ferrill	Ferrill			
3. Address of Operator					9. Well No.	9. Well No.			
P.O. Box 537, Farmington, NM 87499					Hazel No. 1	1			
4. Location of Well					10. Field and Pool, or Wildcat	10. Field and Pool, or Wildcat			
UNIT LETTER H 2310 FEET FROM THE NORTH LINE AND 990 FEET FROM					Wildcat	Wildcat			
UNIT LET	TTER	<del></del>	FEET FROM THE		LINE AND PEET P	THE THE THE THE MOST	$\alpha$		
	Fact		,	1 21			////		
THE	LII	E, SECTION	TOWNSHIP	131	N RANGE 8E NA	лРМ. <b>()   )   )   )   )   )   )   )   )   )  </b>			
15. Elevation (Show whether DF, RT, GR, etc.)					12. County	777			
5884 GR					Santa Fe				
16.	. (	Check Appro	priate Box To Ind	icate N	lature of Notice, Report or	Other Data			
•					ENT REPORT OF:				
PERFORM REI	MEDIAL WORK		PLUG AND ABAN	DON X	REMEDIAL WORK	ALTERING CASING	Щ		
TEMPORARILI	Y ABANDON		÷		COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT			
PULL OR ALT	ER CASING		CHANGE PLANS		CASING TEST AND CEMENT JOB				
					OTHER				
OTHER			·	🗆					
					,				

Subject to your approval, we intend to plug and abandon this well. We will plug from TD to 2100' with 50 sks of cement to cover the perforations at

2740' to 2760'. We will also plug below surface with 10 sks of cement.

President, Black Oil, Inc. DATE February 3,