Office	ate District		e of New M			Form C
<u>District I</u> 1625 N. French Dr., Hobbs, N	Massan	Energy, Mine	erais and Nat	ural Resources	WELL API N	May 27
District II	MI 40240	The state of the s		TOIMEION	30-019-2	
1301 W. Grand Ave., Artesia,	NM 88210			N DIVISION	5. Indicate T	ype of Lease
District III 1000 Rio Brazos Rd., Aztec, I	1M 87410 (7 2005 1220 5	South St. Fra	ncis Dr.	STAT	
District IV 1220 S. St. Francis Dr., Santa	H MONG	San	ita Fe, NM 8	7505	6. State Oil &	c Gas Lease No.
87505	FOR THE STATE OF T	ERVATION			+	
		ES AND REPOR			7. Lease Nan	ne or Unit Agreement Na
(DO NOT USE THIS FORM DIFFERENT RESERVOIR.					Mescaler	0
PROPOSALS.)					8. Well Num	her 1
1. Type of Well: Oil W	7ell ☐ (Gas Well 🔲 Othe	er .			
Name of Operator Labrador 0il	Company				9. OGRID N	umber 82887
3. Address of Operator 23 Cedar S	prings,	#405, Dallas	, Texas 75	5201	10. Pool nam Wild	
4. Well Location						
Unit Letter	E :_	2140 feet fron	n the <u>North</u>	line and	525feet	from the West
Section 1		Townsh	ip 6N R	ange 22E	NMPMGuad	alup@ounty
				R, RKB, RT, GR, et	c.)	
Pit or Below-grade Tank App	lication 🖂 a	Glesure D				
	oucanon ∟ or to Groundwa		nm nacuaet funch	water well D	ictorco fram manus-1	curfaca wotar
-				bbls;		*
Pit Liner Thickness:	mil					
12.	Check A	ppropriate Box	to indicate r	Nature of Notice	e, Report or Ot	ner Data
NOTIC	E OF IN	TENTION TO:		SU	BSEQUENT	REPORT OF:
	WORK [7]		IDON []	1		
PERFORM REMEDIAL		PLUG AND ABAN		REMEDIAL WO	RK [ALTERING CASING
PERFORM REMEDIAL TEMPORARILY ABAND	ои 🔲	PLUG AND ABAN CHANGE PLANS		REMEDIAL WO	RK [RILLING OPNS.[ALTERING CASING PANDA
PERFORM REMEDIAL	ои 🔲	PLUG AND ABAN		REMEDIAL WO	RK [RILLING OPNS.[ALTERING CASING PANDA
PERFORM REMEDIAL TEMPORARILY ABAND PULL OR ALTER CASINOTHER:	OON	PLUG AND ABAN CHANGE PLANS MULTIPLE COMF	2L	REMEDIAL WO COMMENCE DI CASING/CEME OTHER:	RK [RILLING OPNS.[NT JOB [ALTERING CASING P AND A
PERFORM REMEDIAL TEMPORARILY ABAND PULL OR ALTER CASIN OTHER: 13. Describe propose	OON	PLUG AND ABAN CHANGE PLANS MULTIPLE COMF	PL	REMEDIAL WO COMMENCE DE CASING/CEME OTHER: pertinent details, a	RK [RILLING OPNS. NT JOB [und give pertinent	ALTERING CASING PANDA
PERFORM REMEDIAL TEMPORARILY ABAND PULL OR ALTER CASIN OTHER: 13. Describe propose of starting any proposed.	OON	PLUG AND ABAN CHANGE PLANS MULTIPLE COMF	PL	REMEDIAL WO COMMENCE DE CASING/CEME OTHER: pertinent details, a	RK [RILLING OPNS. NT JOB [und give pertinent	ALTERING CASING P AND A dates, including estimate
PERFORM REMEDIAL TEMPORARILY ABAND PULL OR ALTER CASIN OTHER: 13. Describe propose of starting any proposed or recompletion.	OON	PLUG AND ABAN CHANGE PLANS MULTIPLE COMF eted operations. (C	PL	REMEDIAL WO COMMENCE DE CASING/CEME OTHER: pertinent details, a	RK [RILLING OPNS. NT JOB [und give pertinent	ALTERING CASING P AND A dates, including estimate
PERFORM REMEDIAL TEMPORARILY ABAND PULL OR ALTER CASIN OTHER: 13. Describe propose of starting any proposed or recompletion. Plugged and a	PON DON DONG DONG DONG DONG DONG DONG DON	PLUG AND ABAN CHANGE PLANS MULTIPLE COMF eted operations. (C k). SEE RULE 11	Clearly state all 03. For Multip	REMEDIAL WO COMMENCE DE CASING/CEME OTHER: pertinent details, a pole Completions:	RK [RILLING OPNS. NT JOB [und give pertinent Attach wellbore descriptions	ALTERING CASING P AND A dates, including estimate
PERFORM REMEDIAL TEMPORARILY ABAND PULL OR ALTER CASIN OTHER: 13. Describe propose of starting any proposed or recompletion.	ed or complete or	PLUG AND ABAN CHANGE PLANS MULTIPLE COMPETED (C). SEE RULE 11. ent program. de 9 5/8" cas	Clearly state all 03. For Multip	REMEDIAL WO COMMENCE DE CASING/CEME OTHER: pertinent details, a ple Completions: A	RK [RILLING OPNS. NT JOB [und give pertinent Attach wellbore di	ALTERING CASING P AND A dates, including estimate in a proposed comparing the compari
PERFORM REMEDIAL TEMPORARILY ABAND PULL OR ALTER CASIN OTHER: 13. Describe propose of starting any propose of recompletion. Plugged and a Lost drill propose to plugged 25sx @	ed or compleroposed working in side ace 25 surface	eted operations. (Ck). SEE RULE 11. ent program. de 9 5/8" cas sx on CIPB @ , place 4" dr	Clearly state all 03. For Multipsing, CIBP 6190, setry hole ma	REMEDIAL WO COMMENCE DE CASING/CEME OTHER: pertinent details, a ple Completions: A set @ 6190 1 CIBP @ 3460 ork and clean	RK [RILLING OPNS.[NT JOB]	ALTERING CASING P AND A dates, including estimate in a proposed comparing the compari
PERFORM REMEDIAL TEMPORARILY ABAND PULL OR ALTER CASIN OTHER: 13. Describe propose of starting any propose or recompletion. Plugged and a Lost drill propose to plugged to plu	ed or compleroposed working in side ace 25 surface	eted operations. (Ck). SEE RULE 11. ent program. de 9 5/8" cas sx on CIPB @ , place 4" dr	Clearly state all 03. For Multipsing, CIBP 6190, setry hole ma	REMEDIAL WO COMMENCE DE CASING/CEME OTHER: pertinent details, a ple Completions: A set @ 6190 1 CIBP @ 3460 ork and clean	RK [RILLING OPNS.[NT JOB]	ALTERING CASING P AND A dates, including estimate in a proposed comparing the compari
PERFORM REMEDIAL TEMPORARILY ABAND PULL OR ALTER CASIN OTHER: 13. Describe propose of starting any propose of recompletion. Plugged and a Lost drill propose to plugged 25sx @	ed or compleroposed working in side ace 25 surface	eted operations. (Ck). SEE RULE 11. ent program. de 9 5/8" cas sx on CIPB @ , place 4" dr	Clearly state all 03. For Multipsing, CIBP 6190, setry hole ma	REMEDIAL WO COMMENCE DE CASING/CEME OTHER: pertinent details, a ple Completions: A set @ 6190 1 CIBP @ 3460 ork and clean	RK [RILLING OPNS.[NT JOB]	ALTERING CASING P AND A dates, including estimate in a proposed comparing the compari
PERFORM REMEDIAL TEMPORARILY ABAND PULL OR ALTER CASIN OTHER: 13. Describe propose of starting any propose of recompletion. Plugged and a Lost drill propose to plugged 25sx @	ed or compleroposed working in side ace 25 surface	eted operations. (Ck). SEE RULE 11. ent program. de 9 5/8" cas sx on CIPB @ , place 4" dr	Clearly state all 03. For Multipsing, CIBP 6190, setry hole ma	REMEDIAL WO COMMENCE DE CASING/CEME OTHER: pertinent details, a ple Completions: A set @ 6190 1 CIBP @ 3460 ork and clean	RK [RILLING OPNS.[NT JOB]	ALTERING CASING P AND A dates, including estimate in a proposed comparing the compari
PERFORM REMEDIAL TEMPORARILY ABAND PULL OR ALTER CASIN OTHER: 13. Describe propose of starting any propose of recompletion. Plugged and a Lost drill propose to plugged 25sx @	ed or compleroposed working in side ace 25 surface	eted operations. (Ck). SEE RULE 11. ent program. de 9 5/8" cas sx on CIPB @ , place 4" dr	Clearly state all 03. For Multipsing, CIBP 6190, setry hole ma	REMEDIAL WO COMMENCE DE CASING/CEME OTHER: pertinent details, a ple Completions: A set @ 6190 1 CIBP @ 3460 ork and clean	RK [RILLING OPNS.[NT JOB]	ALTERING CASING P AND A dates, including estimate in a proposed comparing the compari
PERFORM REMEDIAL TEMPORARILY ABAND PULL OR ALTER CASIN OTHER: 13. Describe propose of starting any propose of recompletion. Plugged and a Lost drill propose to plugged 25sx @	ed or compleroposed working in side ace 25 surface	eted operations. (Ck). SEE RULE 11. ent program. de 9 5/8" cas sx on CIPB @ , place 4" dr	Clearly state all 03. For Multipsing, CIBP 6190, setry hole ma	REMEDIAL WO COMMENCE DE CASING/CEME OTHER: pertinent details, a ple Completions: A set @ 6190 1 CIBP @ 3460 ork and clean	RK [RILLING OPNS.[NT JOB]	ALTERING CASING P AND A dates, including estimate in a proposed comparing the compari
PERFORM REMEDIAL TEMPORARILY ABAND PULL OR ALTER CASIN OTHER: 13. Describe propose of starting any propose of recompletion. Plugged and a Lost drill propose to plugged 25sx @	ed or compleroposed working in side ace 25 surface	eted operations. (Ck). SEE RULE 11. ent program. de 9 5/8" cas sx on CIPB @ , place 4" dr	Clearly state all 03. For Multipsing, CIBP 6190, setry hole ma	REMEDIAL WO COMMENCE DE CASING/CEME OTHER: pertinent details, a ple Completions: A set @ 6190 1 CIBP @ 3460 ork and clean	RK [RILLING OPNS.[NT JOB]	ALTERING CASING P AND A dates, including estimate in a proposed comparing the compari
PERFORM REMEDIAL TEMPORARILY ABAND PULL OR ALTER CASIN OTHER: 13. Describe propose of starting any propose of recompletion. Plugged and a Lost drill propose to plugged 25sx @	ed or compleroposed working in side ace 25 surface	eted operations. (Ck). SEE RULE 11. ent program. de 9 5/8" cas sx on CIPB @ , place 4" dr	Clearly state all 03. For Multipsing, CIBP 6190, setry hole ma	REMEDIAL WO COMMENCE DE CASING/CEME OTHER: pertinent details, a ple Completions: A set @ 6190 1 CIBP @ 3460 ork and clean	RK [RILLING OPNS.[NT JOB]	ALTERING CASING P AND A dates, including estimate in a proposed comparing the compari
PERFORM REMEDIAL TEMPORARILY ABAND PULL OR ALTER CASIN OTHER: 13. Describe propose of starting any propose of recompletion. Plugged and a Lost drill propose to plugged 25sx @	ed or compleroposed working in side ace 25 surface	eted operations. (Ck). SEE RULE 11. ent program. de 9 5/8" cas sx on CIPB @ , place 4" dr	Clearly state all 03. For Multipsing, CIBP 6190, setry hole ma	REMEDIAL WO COMMENCE DE CASING/CEME OTHER: pertinent details, a ple Completions: A set @ 6190 1 CIBP @ 3460 ork and clean	RK [RILLING OPNS.[NT JOB]	ALTERING CASING P AND A dates, including estimate in a proposed comparing the compari
PERFORM REMEDIAL TEMPORARILY ABAND PULL OR ALTER CASIN OTHER: 13. Describe propose of starting any propose of recompletion. Plugged and a Lost drill propose to plugged 25sx @	ed or compleroposed working in side ace 25 surface	eted operations. (Ck). SEE RULE 11. ent program. de 9 5/8" cas sx on CIPB @ , place 4" dr	Clearly state all 03. For Multipsing, CIBP 6190, setry hole ma	REMEDIAL WO COMMENCE DE CASING/CEME OTHER: pertinent details, a ple Completions: A set @ 6190 1 CIBP @ 3460 ork and clean	RK [RILLING OPNS.[NT JOB]	ALTERING CASING P AND A dates, including estimate in a proposed comparing the compari
PERFORM REMEDIAL TEMPORARILY ABAND PULL OR ALTER CASIN OTHER: 13. Describe propose of starting any propose described and a lost drill propose to propose	ed or complete oposed work in the lace 25 surface 11 comme	PLUG AND ABAN CHANGE PLANS MULTIPLE COMPeted operations. (Cook). SEE RULE 11 de 9 5/8" cas sx on CIPB @, place 4" drace in March,	Clearly state all 03. For Multip sing, CIBP 6190, setry hole ma, weather	REMEDIAL WO COMMENCE DE CASING/CEME OTHER: pertinent details, a cole Completions: A set @ 6190 ork and clean permitting.	RK [RILLING OPNS.[NT JOB]	ALTERING CASING P AND A dates, including estimate in a proposed comparing the compari
PERFORM REMEDIAL TEMPORARILY ABAND PULL OR ALTER CASIN OTHER: 13. Describe propose of starting any propose of recompletion. Plugged and a Lost drill propose to plugged 25sx @	ed or complete oposed work in the inside accessing a comme	PLUG AND ABAN CHANGE PLANS MULTIPLE COMPeted operations. (Cook). SEE RULE 11 de 9 5/8" cas sx on CIPB @, place 4" drance in March,	Clearly state all 03. For Multip sing, CIBP 6190, setry hole ma, weather	REMEDIAL WO COMMENCE DE CASING/CEME OTHER: pertinent details, a cole Completions: A cole Completions: A cole completions and clean permitting.	RK [RILLING OPNS.[NT JOB] Ind give pertinent Attach wellbore did not a location.	ALTERING CASING P AND A dates, including estimate in a proposed compared to the compared to t
PERFORM REMEDIAL TEMPORARILY ABAND PULL OR ALTER CASIN OTHER: 13. Describe propose of starting any propose to place 25sx @ This work will I hereby certify that the ingrade tank has been/will be co	ed or complete oposed work in the inside accessing a comme	PLUG AND ABAN CHANGE PLANS MULTIPLE COMPeted operations. (Cook). SEE RULE 11 de 9 5/8" cas sx on CIPB @, place 4" drance in March,	Clearly state all 03. For Multip sing, CIBP 6190, setry hole may weather	REMEDIAL WO COMMENCE DE CASING/CEME OTHER: pertinent details, a ple Completions: A Set @ 6190 1 CIBP @ 3460 rk and clean permitting.	RK [RILLING OPNS.[NT JOB] and give pertinent Attach wellbore did not a location.	ALTERING CASING P AND A dates, including estimate in a proposed compared to the compared proposed compared to the compared proposed compared to the compared proposed plant the certify that any pit or iternative OCD-approved plant the certify that any pit or iternative OCD-approved plant the certify that any pit or iternative OCD-approved plant the certify that any pit or iternative OCD-approved plant the certify that any pit or iternative OCD-approved plant the certify that any pit or iternative OCD-approved plant the certify that any pit or iternative OCD-approved plant the certify that any pit or iternative OCD-approved plant the certify that any pit or iternative OCD-approved plant the certify that any pit or iternative OCD-approved plant the certify that any pit or iternative OCD-approved plant the certify that any pit or iternative OCD-approved plant the certify that any pit or iternative OCD-approved plant the certify that any pit or iternative OCD-approved plant the certify that any pit or iternative OCD-approved plant the certify that any pit or iternative OCD-approved plant the certify that any pit or iternative OCD-approved plant the certification the c
PERFORM REMEDIAL TEMPORARILY ABAND PULL OR ALTER CASIN OTHER: 13. Describe propose of starting any propose to place 25sx @ This work will I hereby certify that the ingrade tank has been/will be co	ed or complete oposed work in the inside accessing a comme	PLUG AND ABAN CHANGE PLANS MULTIPLE COMPeted operations. (Cook). SEE RULE 11 de 9 5/8" cas sx on CIPB @, place 4" drance in March,	Clearly state all 03. For Multip sing, CIBP 6190, setry hole may weather	REMEDIAL WO COMMENCE DE CASING/CEME OTHER: pertinent details, a cole Completions: A cole Completions: A cole completions and clean permitting.	RK [RILLING OPNS.[NT JOB] and give pertinent Attach wellbore did not a location.	ALTERING CASING P AND A dates, including estimate in a proposed compared to the compared to t
PERFORM REMEDIAL TEMPORARILY ABAND PULL OR ALTER CASIN OTHER: 13. Describe propose of starting any propose to place 25sx @ This work will I hereby certify that the ingrade tank has been/will be co	ed or complete oposed work in the inside accessing a comme	PLUG AND ABAN CHANGE PLANS MULTIPLE COMPeted operations. (Cook). SEE RULE 11 de 9 5/8" cas sx on CIPB @, place 4" drance in March,	Clearly state all 03. For Multip sing, CIBP 6190, setry hole may weather	REMEDIAL WO COMMENCE DE CASING/CEME OTHER: pertinent details, a ple Completions: A Set @ 6190 ork CIBP @ 3460 ork and clean permitting.	RK [RILLING OPNS.[NT JOB] and give pertinent Attach wellbore did not a location.	ALTERING CASING P AND A dates, including estimate in a proposed compared to the compared proposed compared to the compared proposed compared to the compared proposed plant the certify that any pit or iternative OCD-approved plant the certify that any pit or iternative OCD-approved plant the certify that any pit or iternative OCD-approved plant the certify that any pit or iternative OCD-approved plant the certify that any pit or iternative OCD-approved plant the certify that any pit or iternative OCD-approved plant the certify that any pit or iternative OCD-approved plant the certify that any pit or iternative OCD-approved plant the certify that any pit or iternative OCD-approved plant the certify that any pit or iternative OCD-approved plant the certify that any pit or iternative OCD-approved plant the certify that any pit or iternative OCD-approved plant the certify that any pit or iternative OCD-approved plant the certify that any pit or iternative OCD-approved plant the certify that any pit or iternative OCD-approved plant the certify that any pit or iternative OCD-approved plant the certify that any pit or iternative OCD-approved plant the certification the c

APPROVED BY: 9 Conditions of Approval (itany):