

District II1301 W. Grand Ave., Artesia, NM 88210
Phone:(505) 748-1283 Fax:(505) 748-9720District III1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170District IV1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462**State of New Mexico**
Energy, Minerals and Natural Resources**Oil Conservation Division**
1220 S. St Francis Dr.
Santa Fe, NM 87505WELL API NUMBER
30-021-205095. Indicate Type of Lease
S

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name
STATE8. Well Number
1629. OGRID Number
49510. Pool name or Wildcat
See Area 13**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: C

2. Name of Operator

HESS CORPORATION

3. Address of Operator

P.O. BOX 840, SEMINOLE, TX 79360

4. Well Location

Unit Letter G : 1650 feet from the N line and 1650 feet from the E line
Section 16 Township 18N Range 30E NMPM Harding County

11. Elevation (Show whether DR, KB, BT, GR, etc.)

4372 GR

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit Type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data**NOTICE OF INTENTION TO:**PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐TEMPORARILY ABANDON ☐ CHANGE OF PLANS ☐PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

Other:

SUBSEQUENT REPORT OF:REMEDIAL WORK ☐ ALTER CASING ☐COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDON ☐CASING/CEMENT JOB ☐Other: **Perforations/Tubing**☒13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.
swabbed csg. to leave fl @ 1300'

RU Schlumberger and perf csg. perforated with 3 3/8" /HSD csg gun from 1984 - 1989. RU w/ 2 7/8" HSD csg gun and perf from 1964 - 1972, ran 3rd gun 2 7/8" HSD csg gun and perf from 1976 - 1980.

Perforations**Pool: WEST BRAVO DOME CO2 GAS, 96387 Location: G -16-18N-30E 1650 N 1650 E**

TOP	BOT	Open Hole	Shots/ft	Shot Size	Material	Stimulation	Amount
1964	1972	Y	4	2.875			
1976	1980	Y	6	2.875			
1984	1989	Y	6	3.475			

TubingI hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐ .SIGNATURE Electronically Signed TITLE Engineering Tech DATE 5/14/2010Type or print name Rita Smith E-mail address rsmith@hess.com Telephone No. 432-758-6726**For State Use Only:**APPROVED BY: Ed Martin TITLE District Supervisor DATE 5/24/2010 2:30:12 PM