<i>Ceived by UCD: 3/19/2021 2:49:01 PM</i> U.S. Department of the Interior BUREAU OF LAND MANAGEMENT		Sundry Print Repor
Well Name: FEDERAL HQ	Well Location: T21S / R22E / SEC 5 / SESW /	County or Parish/State: EDDY / NM
Well Number: 1	Type of Well: CONVENTIONAL GAS WELL	Allottee or Tribe Name:
Lease Number: NMNM21012	Unit or CA Name:	Unit or CA Number:
US Well Number: 300152212000S1	Well Status: Gas Well Shut In	Operator: EOG RESOURCES INCORPORATED

Accepted for record – NMOCD gc 5/19/2021

Type of Action Plug and Abandonment

Time Sundry Submitted: 11:08

Notice of Intent

Type of Submission: Notice of Intent

Date Sundry Submitted: 05/12/2021

Date proposed operation will begin: 05/24/2021

Procedure Description: Please see attached. Thank you.

Surface Disturbance

Is any additional surface disturbance proposed?: No

NOI Attachments

Procedure Description

Federal_HQ_1_5_12_21_20210512110842.pdf

Conditions of Approval

Specialist Review

Federal_HQ_1_Sundry_ID_2386937_P_A_20210516111745.pdf

0

Received by OCD: 5/19/2021 2:49:01 PM Well Name: FEDERAL HQ	Well Location: T21S / R22E / SEC 5 / SESW /	County or Parish/State: EDDY / NM
Well Number: 1	Type of Well: CONVENTIONAL GAS WELL	Allottee or Tribe Name:
Lease Number: NMNM21012	Unit or CA Name:	Unit or CA Number:
US Well Number: 300152212000S1	Well Status: Gas Well Shut In	Operator: EOG RESOURCES INCORPORATED

Operator Certification

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a submission of Form 3160-5 or a Sundry Notice.

Operator Electronic Signature: TINA HUERTA Name: EOG RESOURCES INCORPORATED Title: Regulatory Specialist Street Address: 104 SOUTH FOURTH STREET City: Artesia State: NM Phone: (575) 748-4168

Email address: tina_huerta@eogresources.com

Field Representative

Representative Name: Street Address: City: State: Phone: Email address:

BLM Point of Contact

BLM POC Name: LONG VO BLM POC Phone: 5752345972 Disposition: Approved Signature: Long Vo

BLM POC Title: Petroleum Engineer BLM POC Email Address: lvo@blm.gov Disposition Date: 05/16/2021

Zip:

Signed on: MAY 12, 2021 11:08 AM



APT: 30-015- 22120

EOG Resources, Inc. plans to plug and abandon this well as follows:

- 1. MIRU all safety equipment as needed. NU BOP. POOH with production equipment.
- 2. Spot a 41 5x Class H cement plug from 8140 ft 7778 ft. WOC and tag. This will cover Atoka perfs and top and also filling cement remnant zone.
- 3. Set a CIBP at 6339 ft with 9 sx Class H cement on top to 6265 ft. This will cover Strawn perfs and L Canyon top. 59% 4. Set a CIBP at 5970 ft with 4 sx Class C cement on top to 5985 ft. This will cover Canyon perfs. Leak test ccBP
- 5. Spot a 34 sx Class C cement plug from 4734 ft 4588 ft. WOC and tag. This will cover Wolfcamp (5, 0) top. kogo
- top. 10^{-76} 6. Perforate at 3601 ft. Spot a 32 sx Class C cement plug from 3601 ft 3466 ft. WOC and tag. This
- will cover Abo top. 7. Perforate at 1553 ft. Spot a 27 sx Class C cement plug from 1553 ft 1438 ft. WOC and tag. This will cover Glorieta top
- will cover Glorieta top.
 8. Perforate at 1156 ft. Spot a 26 sx Class C cement plug from 1156 ft 1045 ft. WOC and tag. This will cover Surface casing shoe.
 9. Perforate at 50 ft. Spot a 12 sx Class C cement plug from 50 ft up to surface. WOC and tag. Back
- fill as needed.
- 10. Cut off wellhead and install dry hole marker. Clean location as per regulated.

Wellbore schematics attached

	Federal HQ #1	S	Sec-TWN-RNG: Sec. 5-21S-22E FOOTAGES: 990' FSL & 1980' FWL	: Sec. 5-21 : 990' FSL 8	S-22E 1980' FWL	Surveyor Balancia Balancia Para da este se da barran	API: GL: VD:	API: 30-015-22120 GL: 4314 VD:	20			OCD: 5
Plug #8							Ś					5/19)
		CASI	9				da		-	004710	TOT slothod	/202
7# guid		* <	HOLE SIZE	SIZE	WGHT 24	GKADE	do c		ax um 775	Circ	Por Inicial And	21 2
	z.	< 0	-	5 1/2	17/15.5		0	-	405		TOC @5500	2:4
Plug #6	And and a second	1		Squeeze Remediation	diation		4,030		200	4030	Tag	9:0
6 6												01
		FORM	FORMATION TOPS									PN
Plug #5			Formation	Top		Formation	Top	Formation	ation Top			1
	 For an and the second se		Glorieta	1495		Atoka	7828			a social de la desta de mais de la compañía de la desta de la d		
			Abo	3533		Morrow Cl	8176			Server excepts at the back of the server excepts		
Sqz, TOC - 4030'			wc	4684		Miss	10000					
Sqz. Hole between 4100' - 4132'			L Canyon	6315								
The Drame and the second second			DUGWI					-				
BOC Unknown		TUBI	TUBING DETAIL									
Plug #4		*	Joints	Description	Length	go	Q	Grade Wt	V/1 (Ib/ft): T	Top (ftKB);	Btm (ftKB):	
Original TOC @5550'												
,									_			
Ptug #3	I	PLUGS	2S									
Canyon Pefs 6020' - 6110'		*	SX	Class	Top	Bottom	Ø		Notes		Tag	
		-	9750	Ŧ	7778	8140	362	Atoka porfs/top (also filling coment remnant zone)	tso filling coment	remnant zone)		
		2		H	6265	-	74	Strawn Perfs & L. Canyon Top	L Canyon Top			I OAK trat CTBP
Plug #2		e	××	J	5985543-0	6 5970	35	Canyon Perfs				
Strawn Perfs 6389' - 6410'		84 7 4	3440	U	4588	4734	146	Wolfcamp Top			~~~~~	(Lug) - C
		5	32.45	0	3466 34	3601	135	Abo Top				
	5	9	222	0	1938 M3	0 1553	115	Glorieta Top				Voiky Courtace
		7	26 26	0	1045 0	1156	111	Sur. Csg. Shoe		And a set of the set o		
Strawn Perts 7538' - 7695'		00	12	o	0	60	50	Surface Plug			>	
									And D. Constant in succession of the succession			
Cmt. Remnant 7868" - 7918' [4.75" ID milt)	(ilm Ci *											
		ADD	ADDITIONAL DETAIL									
Packer @ 7828'		1.18	1.18.2001 Packer left at 7828' [removed for proposed P&A]	7828' [remover	I for proposed F	78,A]						
Atoka Perfs 7967' - 8090'			Cement remn	ants from 4045	' - 5000' & 7866	Cement remnants from 4045' - 5000' & 7865' - 7915' remaining from 4.75' mill	ning from 4.7:	5" mill				
Plug #1												
Fish (CIBP] - 8142'		PER	PERFORATION DETAIL					و در استور به مروز با دور با موسود می مروز .				
EOC @ 8240'			Formation	Top	Bottom							
Existing Cmt Plug 8250' - 8350'			Atoka	7967	2 8090	0						
			Strawn	7538	7695	5				والمحافظة والمحافظة المتحافظ والمراجع والمراجع والمحافظ والمحافظ والمحافظ		
			Strawn	6389		5				1944 - - - - - - - - - - - -		
	00		Canyon	6020	0 6110	0				والمركز المرابع الاستحداد والمستعم والمراسية والمرابع والمواسعهم		
	7,883					Prepai	Preparted by: KJP					Pa
	TD: 8,679 MD											ige

Released to Imaging: 5/25/2021 3:43:35 PM

					1 4 4 4	STATISTICS CONTRACTOR	000 E 74	5 375		ADI-120	ADI-120.045.22420	-		
Fede	Federal HQ #1	0 #1				FOOTAGES- 990' FSL & 1980' FWL	990' FSL &	3-4.4L	7	GI: 4314	14	2		
					-	222				i iii				
				1										
Destance.					CASING DETAIL	ETAIL								
					+	HOLE SIZE	SIZE	WGHT	GRADE	Top	Bottom	Sx Cmt	Circ/TOC	TOC Method
					A	12 1/4	8 5/8	24		0	1,100	775	Circ	
	$\langle $			/1	8	7 7/8	5 1/2	17/15.5		0	8,240	405		TOC @5500
	A					Sque	Squeeze Remediation	ation		4,030	5,500	200	4030	Tag
											ففاحتها الأشادة فالمسدم بالمحالي والماجونية فالمعاوية			
				L										
					FORMATION TOPS	SN TOPS	And the second se		A STATUS OF A DESCRIPTION OF A DESCRIPTI					
							Exemation	Ton		Eo	Formation		Top	
					T		Classes	1/0/						
542. LUC - 4030							GIOLIEIa	0040						
342. HOIB DETWOON 4100' - 4132'				<u></u>			WC	4684						
Cmt. Remnant 4045'-5000' [4,75" ID mill]							L Canyon	6315						
BOC Unknown							Strawn	6758						
*10.000				L			Atoka	7828						
							Morrow Cl	8176						
Original TOC (05550'							Miss	8583						
		1.11.1									and a second			
Canyon Pefs 6020' - 6110'		000												
												A CONTRACTOR OF		
										10.000				
					TUBING DETAIL	DETAIL	Red American American American American					100 m m	The second	0101 (8/10)
					#	Joints	Description	Length	00	0	Grade	WI (ID/II):	1 op (TINE):	10011 (1100)
Strawn Perfs 6389' - 6410'		m	And			2 3/8 tubing					a a de la constante de la const			979/
							and and a set of the set of the			AND ADDRESS OF			ANALAS STATISTICS	
		0.00			ADDITION	IAL DETAIL	A REAL PROPERTY AND A REAL							
Strawn Perfs 7538' - 7695'		m			1.18.2001	1.18.2001 Packer left at 7828'	828'					tables. I want to be a set of the		
		igen).				Cement remnal	nts from 4045	Cement remnants from 4045' - 5000' & 7866' - 7918' remaining from 4.75" mill	s' - 7918' ref	naining fr	om 4.75" mill	And a book of the second		
Cmt. Remnant 7868' - 7918' [4.75" [D mill)														
					PERFORM	PERFORATION DETAIL				a da anna an			************	
						Formation	Top	Bottom	Treatment	1		and the submative of the second se		
Packer @ 7828'		M	M		A	Aloka	8076		5090 Acized w/1000g 7 1/2% MS acid	1000 7 1/2%	MS acld			
Atoka Perts 7967' - 8090'		(111)	And			Atoka	7967		B Acldized w/	2000g MS a	7978 Acidized w/2000g MS acid & Nilrogen 15000g 2% acid & c02	000g 2% acid	\$. c02	
Fish [CIBP] - 8142'		2	6			Strawn	7538		7695 Acidized w/2000 g 7 1/2% MCA acid	2000 g 7 1/2	2% MCA acid		والمحافظة والمحافظة المحافظة والمحافظة	
Î		5				Strawn	6389		6410 Acidized w/1500 g 15% NEFE	1500 9 15%	, NEFE			
EOC @ 8240	7	-	/			Canyon	6100		6110 1000 g 15% DS-30 acid	DS-30 acid	P	ney a ginada daye nyana yana nang kabap		
Existing Cmt Plug 8250' - 8350'					L	Canyon	6020		6032 1000g 15% DS-30 acid	DS-30 acid				
	00											and the second		
			0											
	1D: 8	8,679 MD	0		DKC 1/20/2021	/2021	And the second second second							

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within **<u>ninety (90)</u>** days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Dry Hole Marker: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. Show date well was plugged.

8. Trash: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

Received by OCD: 5/19/2021 2:49:01 PM



United States Department of the Interior

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



Page 8 of 10

In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3). Surface Use Plan of 1. Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.

2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.

- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation. equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify

5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.

6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been

achieved and the location and/or access road is ready for a final abandonment inspection. 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work

needed or additional time being needed to achieve the objective. If there are any questions, please feel free to contact any of the following specialists:

Supervisory Petroleum Engineering Tech 575-234-5909 (Office), 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crisha Morgan Environmental Protection Specialist 575-234-5987

Melissa Horn Environmental Protection Specialist 575-234-5951

Kelsey Wade Environmental Protection Specialist 575-234-2220

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	28872
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)
	•

CONDITIONS

Created By	Condition	Condition Date
gcordero	None	5/24/2021

CONDITIONS

Page 10 of 10

Action 28872