U.S. Department of the Interior BUREAU OF LAND MANAGEMENT		Sundry Print Repor
Well Name: BELLAGIO BBY FEDERAL	Well Location: T20S / R25E / SEC 33 / NENE /	County or Parish/State: EDDY / NM
Well Number: 2	<b>Type of Well:</b> CONVENTIONAL GAS WELL	Allottee or Tribe Name:
Lease Number: NMNM108453	Unit or CA Name:	Unit or CA Number:
US Well Number: 300153408400D1	Well Status: Producing Gas Well	<b>Operator:</b> EOG RESOURCES INCORPORATED

### Accepted for record – NMOCD gc 5/19/2021

Type of Action Plug and Abandonment

Time Sundry Submitted: 04:28

## Notice of Intent

Type of Submission: Notice of Intent

Date Sundry Submitted: 05/11/2021

Date proposed operation will begin: 05/17/2021

Procedure Description: Please see attached.

## **Surface Disturbance**

Is any additional surface disturbance proposed?: No

### **NOI Attachments**

### **Procedure Description**

Bellagio\_BBY\_Federal\_2\_5\_11\_21\_20210511162748.pdf

## **Conditions of Approval**

### **Specialist Review**

Bellagio\_BBY\_Federal\_2\_Sundry\_ID\_2386826\_P\_A\_20210516111600.pdf

10

R	eceived by OCD: 5/19/2021 2:47:16 PM Well Name: BELLAGIO BBY FEDERAL	Well Location: T20S / R25E / SEC 33 / NENE /	County or Parish/State: EDDY / NM
	Well Number: 2	<b>Type of Well:</b> CONVENTIONAL GAS WELL	Allottee or Tribe Name:
	Lease Number: NMNM108453	Unit or CA Name:	Unit or CA Number:
	US Well Number: 300153408400D1	Well Status: Producing Gas Well	<b>Operator:</b> EOG RESOURCES INCORPORATED

## **Operator Certification**

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a submission of Form 3160-5 or a Sundry Notice.

Operator Electronic Signature: TINA HUERTA Name: EOG RESOURCES INCORPORATED Title: Regulatory Specialist Street Address: 104 SOUTH FOURTH STREET City: Artesia State: NM Phone: (575) 748-4168

Email address: tina\_huerta@eogresources.com

State:

## Field Representative

Representative Name: Street Address: City: Phone: Email address:

### **BLM Point of Contact**

BLM POC Name: LONG VO BLM POC Phone: 5752345972 Disposition: Approved Signature: Long Vo

BLM POC Title: Petroleum Engineer BLM POC Email Address: lvo@blm.gov Disposition Date: 05/16/2021

Zip:

Signed on: MAY 11, 2021 04:28 PM

## APZ: 30-015-34084

EOG Resources, Inc. plans to plug and abandon this well as follows:

- 1. MIRU all safety equipment as needed. NU BOP. POOH with production equipment.
- 2. Set a CIBP at 9524 ft with X sx Class H cement on top to 9489 ft. WOC and tag. This will cover Morrow perfs. 85
- 3. Spot a 36 sx Class H cement plug from 9306 ft 9114 ft. This will cover Atoka top.
- 4. Spot a 36 sx Class H cement plug from 8869 ft 8681 ft. This will cover Strawn top.
- 5. Spot a 34 sx Class H cement plug from 7874 ft 7696 ft. This will cover Cisco Canyon top.
- 6. Set a CIBP at 7298 ft with & Class C cement on top to 7263 ft. This will cover Wolfcamp perfs. Leak fest CIBP WOC &TA V

High lave

- 7. Spot a 28 sx Class C cement plug from 6729 ft 6561 ft. This will cover 3rd Bone Spring top.
- 8. Spot a 26 sx Class C cement plug from 5261 ft 5109 ft. This will cover 2<sup>nd</sup> Bone Spring top. WOC & THK
- 9. Perforate at 3656 ft. Spot a 3235 Class C cement plug from 3656 ft 3470 ft. WOC and tag. This will cover Bone Spring top and Intermediate casing shoe. 39 9x WOC KAK
- 10. Spot a 49 sx Class C cement plug from 2885 ft 2595 ft. This will cover Upper Yeso and Glorieta 5 rSCR top. WOCGTALT
- 11. Spot a 25 sx Class C cement plug from 1010 ft 860 ft. This will cover San Andres top.
- 12. Perforate at 858 ft. Spot a 25 sx Class C cement plug from 858 ft 726 ft. WOC and tag. This will cover TOC.
- 13. Perforate at 469 ft. Spot a 103 sx Class C cement plug from 469 ft up to surface. WOC and tag. Back fill as needed. (m(0x) Verity @ surface
- 14. Cut off wellhead and install dry hole marker. Clean location as per regulated.

Wellbore schematics attached



#### Received by OCD: 5/19/2021 2:47:16 PM

Released to Imaging: 5/25/2021 3:43:04 PM

Page 4 of 10

					2	OTAGES:	1310' FNI	FUUIAGES: 1310' FNL & 660' FEL	L	GL: 3633 KB: 3651	GL: 3633 KB: 3651			
					CASING DETAIL	ETAIL				No of Charles in the second				
					9H #	HOLE SIZE	SIZE	WGHT	GRADE	Top 1	Bottom	Sx Cmt	Circ/TOC	TOC Method
					A	17 1/2	13 3/8	48	H-40	0	419	440	Circ	
					83	12 1/4	8 5/8	36	J-55			1000	Circ	
	\ \			_/	0	8 3/4	7	23,26			10,000	1220	TOC	
				1						+				
	unui: 034													
					CODIGATION TODO	MI TODO								
					LONWAIN	Γ	Г							
								Top		<u>щ</u>	Formation	Top	a	
	423						San Andres	935		W	Middle Morrow		9615	
							Clorietta	2645		107	Lower Morrow	*	9785	
	262						Upper Yeso	2835	10	ឌ័	Base of Morrow	MO	9860	
	490						Rone Springs Line	3545						
							2nd Bone Springs	5185						
					- In the second s		3rd Bone Springs	6645						
							Wolfcamp	6845					and a second	
	949 <u>8</u> 9	1					Cisco Canyor	7785						
	ß			/			Strawn	8775		-		_		
				ł		1	Atoka				And a state of the			
							Upper Morrow	(						
							$\left \right\rangle$							AN ALL HANKING
					TUBING DETAIL	TAIL								
			]		*	Joints	Description	Length	ao	0	Grade Wt	Wt (Ib/fit)	Ton (#KB)-	Rtm (HKB)-
			A Contraction of the Contraction		r-		2-7/8" Tubing and packer	and packer		-			0 925	
			1		2		2-718" Tubino						2,000	
							Rillon Di		Conceptibility of the second se	STREET, STREET	2010010101010100	Arrest and a state of the	7,300	1.6.1.6.1.6.1.6.1.6.1.6.1.6.1.6.1.6.1.6
				L										
				]										
				1999										SUBSCRIPTION STATES
	Packer	X	K	Ma	Perforation Detail	Detail								
		ð		l	Form	Formation T	Top	Bottom	1	Treatment				
				41	A Morrow	-WW	9,574	9,584		cidized wi	th1000a M	SA acid w/3	Acidized with1000g MSA acid w(3000 SCF N2/bbt	
			Construction of the second sec							ac w/CO2	foam frac	sidd 496/w	Frac w/CO2 foam frac w/394 bbls fluid20 300# 20140 varsa mmo	In varea nr
				<u> </u>	B Wolf	Wolfcamp	7 348	7 286		Church with	1000 - 0000		-107 -1000 07000	TH PEIDA OF
				L				2021			0/07 B000		Vuluite W/2000 20% IC UCL gelled acid W//0 ball sealers	sealers
				L]										
														مغطاته وتسميه محمد محتجب خلافك
	υ		1	1										Second
		Z	4											
in Arraigna	PBTD:	9,958									and the second			
*******			2											

,

.

## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Permanent Abandonment of Federal Wells **Conditions of Approval**

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within **<u>ninety (90)</u>** days from the approval date of this

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. Notification: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a

4. Mud Requirement: Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Dry Hole Marker: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well.

8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

#### Received by OCD: 5/19/2021 2:47:16 PM



# United States Department of the Interior

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

### Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads. facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909 (Office), 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crisha Morgan Environmental Protection Specialist 575-234-5987

Melissa Horn Environmental Protection Specialist 575-234-5951

Kelsey Wade Environmental Protection Specialist 575-234-2220

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

## **State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	28871
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

#### CONDITIONS

Created By	Condition	Condition Date
gcordero	None	5/24/2021

CONDITIONS

Page 10 of 10

Action 28871