

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-015-33146
5. Indicate Type of Lease STATE [ ] FEE [X]
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Harroun "A"
8. Well Number 7
9. OGRID Number 22767
10. Pool name or Wildcat Herradura Bend: Delaware
11. Elevation (Show whether DR, RKB, RT, GR, etc.) KB 3048

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)
1. Type of Well: Oil Well [X] Gas Well [ ] Other [ ]
2. Name of Operator The Eastland Oil Company
3. Address of Operator P.O. Drawer 3488 Midland, TX 79702
4. Well Location Unit Letter M : 330 feet from the SOUTH line and 530 feet from the WEST line
Section 28 Township 22S Range 28E NMPM EDDY County

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK [ ] PLUG AND ABANDON [ ]
TEMPORARILY ABANDON [X] CHANGE PLANS [ ]
PULL OR ALTER CASING [ ] MULTIPLE COMPL [ ]
DOWNHOLE COMMINGLE [ ]
CLOSED-LOOP SYSTEM [ ]
OTHER: [ ]
SUBSEQUENT REPORT OF:
REMEDIAL WORK [ ] ALTERING CASING [ ]
COMMENCE DRILLING OPNS. [ ] P AND A [ ]
CASING/CEMENT JOB [ ]
OTHER: [ ]

Notify OCD 24 hrs. prior to any work done

- 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.
1. MRU pulling unit. Ensure guidelines are secured to anchors, ensure there is a clear path for all trucks to circle the rig and any H2S equipment is rigged up.
2. Check Braden head and tubing head for pressure, bleed off any pressure and check for flow. If flow occurs kill well before continuing. If no flow prepare wellhead to pull down hole equipment. Record pressures in daily report. Load and test tubing to 1000 psi.
3. NU rod BOPs
4. Rig up elevators to pull all rods and pump. Rack back rods in monkey board, wipe rods on the way out. Check Rod grade every 10 triples on TOH. Pull bottom hole equipment.
5. Send pump to Precision Pump in Loco Hills for repair.
6. Change out rod elevators for 2 3/8" tubing elevators. NUBOP, Release TAC, tally out of hole and stand tubing in derrick. (XX jts, 2,480')
7. Make up bit and scraper on tubing. TIH with bit and scraper to clean casing. TOO H with bit and scraper.
8. Make up retrievable bridge plug on tubing and TIH to set packer at 2,425' (50' above production casing shoe). Unlatch from the packer and PU tbg. Fill hole with packer fluid.
9. Pressure test 5-1/2" production casing to 500 psi for 30 minutes on a chart recorder with a maximum two hour clock and maximum 1000 pound spring, which has been calibrated within the six months prior to conducting the test. Witnesses to the test shall sign the chart. During pressure test, open all other casing valves and report a flow or pressure change occurring immediately before, during or immediately after the 30 minute pressure test.
10. TOO H with tubing and lay down same.
11. Top off casing with packer fluid. SWI. RDMO pulling unit.

Spud Date:

[Empty box for Spud Date]

Rig Release Date:

TA status may be granted after a successful MIT test is performed. Contact the OCD to schedule the test so it may be witnessed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Michael Thompson TITLE Engineer DATE 5/10/22

Type or print name Michael Thompson E-mail address: mthompson@Eastlandoil.com PHONE: 432.683.6293
For State Use Only

APPROVED BY: [Signature] TITLE Staff Manager DATE 6/7/2022
Conditions of Approval (if any):

# THE EASTLAND OIL COMPANY

Harroun "A" #7  
API 30-015-33146  
Herradura Bend  
Eddy County, New Mexico

## Temporarily Abandon Well

Purpose: Temporarily abandon well to evaluate potential for pressure maintenance injection well.

### Cleanout

1. MIRU pulling unit. Ensure guidelines are secured to anchors, ensure there is a clear path for all trucks to circle the rig and any H2S equipment is rigged up.
2. Check Braden head and tubing head for pressure, bleed off any pressure and check for flow. If flow occurs kill well before continuing. If no flow prepare wellhead to pull down hole equipment. Record pressures in daily report. Load and test tubing to 1000 psi.
3. NU rod BOPs
4. Rig up elevators to pull all rods and pump. Rack back rods in monkey board, wipe rods on the way out. Check Rod grade every 10 triples on TOH. Pull bottom hole equipment.
5. Send pump to Precision Pump in Loco Hills for repair.
6. Change out rod elevators for 2 3/8" tubing elevators. NUBOP, Release TAC, tally out of hole and stand tubing in derrick. (XX jts, 2,480')
7. Make up bit and scraper on tubing. TIH with bit and scraper to clean casing. TOOH with bit and scraper.
8. Make up retrievable bridge plug on tubing and TIH to set packer at 2,425' (50' above production casing shoe). Unlatch from the packer and PU tbg. Fill hole with packer fluid.
9. Pressure test 5-1/2" production casing to 500 psi for 30 minutes on a chart recorder with a maximum two-hour clock and maximum 1000-pound spring, which has been calibrated within the six months prior to conducting the test. Witnesses to the test shall sign the chart. During pressure test, open all other casing valves and report a flow or pressure change occurring immediately before, during or immediately after the 30-minute pressure test.
10. TOOH with tubing and lay down same.
11. Top off casing with packer fluid. SWI. RDMO pulling unit.


MT

## Wellbore Schematic

**Harroun A #7**

330' FSL 530' FWL  
 M-Sec 28 TS22S R28E  
 Eddy County, NM  
 First Produced 2/5/04

API # 30-015-33146  
 Lat  
 Long  
 IP: Oil, Mcf, Water



2" X 1-1/2" X 12'  
**Strokes per minute:**  
**Stroke Length:**  
**Last crank hole**  
**Pump Displacement:** per day


**KB:** 3048  
**D.F.**  
**G.L.** 3036

### Proposed Wellbore Schematic

**Harroun A #7**

330' FSL 530' FWL  
 M-Sec 28 TS22S R28E  
 Eddy County, NM  
 First Produced 2/5/04

API # 30-015-33146  
 Lat  
 Long  
 IP: Oil, Mcf, Water



**Hole: 12 1/4"**  
 434'  
**Top of cement**  
 Surface  
 208 sx Class C & CaCl

**Surface Casing**  
 8 5/8" 24# K-55  
 420'

Casing filled with inert  
 packer fluid

**Hole: 7 7/8"**  
 2,476'  
**Top of Cement**  
 Surface  
 154 sx lead & 247 sx 50-50  
 POZ + 2% D20 + 0.2% D46

**Retrievable Bridge Plug**  
 2,425'

**Perforations**  
 Openhole

**Long String Csg.**  
 5 1/2" 14# K-55  
 2,475'

**Hole Size**  
 4 3/4"

**Total Depth**  
 2,510'

Strokes per minute:  
 Stroke Length:  
 Last crank hole  
 Pump Displacement: per day

KB: 3048  
 D.F.  
 G.L. 3036

**District I**  
 1625 N. French Dr., Hobbs, NM 88240  
 Phone:(575) 393-6161 Fax:(575) 393-0720

**District II**  
 811 S. First St., Artesia, NM 88210  
 Phone:(575) 748-1283 Fax:(575) 748-9720

**District III**  
 1000 Rio Brazos Rd., Aztec, NM 87410  
 Phone:(505) 334-6178 Fax:(505) 334-6170

**District IV**  
 1220 S. St Francis Dr., Santa Fe, NM 87505  
 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 105932

**CONDITIONS**

Operator: EASTLAND OIL CO P.O. Box 3488 Midland, TX 79702	OGRID: 22767
	Action Number: 105932
	Action Type: [C-103] NOI Temporary Abandonment (C-103I)

**CONDITIONS**

Created By	Condition	Condition Date
gcordero	None	6/7/2022